UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

25-FEB-2017 TIME: 0430 HOURS CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. X INCIDENT >\$25K Telescopic Man Basket H2S/15MIN./20PPM pedestal CONTRACTOR: REPRESENTATIVE: TELEPHONE: CONTRACTOR: REPRESENTATIVE: TELEPHONE: 3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT: 4. LEASE: G35153 AREA: AC LATITUDE: BLOCK: 772 LONGITUDE: 5. PLATFORM: RIG NAME: NOBLE GLOBETROTTER 6. ACTIVITY: X EXPLORATION(POE) DEVELOPMENT/PRODUCTION REQUIRED EVACUATION HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. Telescopic Man Basket H2S/15MIN./20PPM pedestal OTHER OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. X INCIDENT >\$25K Telescopic Man Basket H2S/15MIN./20PPM pedestal REQUIRED MUSTER REQUIRED MUSTER BEQUIRED MUSTER FRODUCTION X DRILLING WORKOVER COMPLETION HELICOPTER OTHER OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. Telescopic Man Basket H2S/15MIN./20PPM pedestal OTHER OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. Telescopic Man Basket H2S/15MIN./20PPM pedestal OTHER 6. OPERATION: FRODUCTION WORKOVER COMPLETION HELICOPTER OTHER OTHER OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. Telescopic Man Basket H2S/15MIN./20PPM pedestal OTHER OTHER H2S/15MIN./20PPM pedestal OTHER OTHER H2S/15MIN./20PPM pedestal OTHER OTHER OTHER OTHER H2S/15MIN./20PPM pedestal OTHER OT	
ON SITE AT TIME OF INCIDENT: 4. LEASE: G35153 AREA: AC LATITUDE: BLOCK: 772 LONGITUDE: COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER 6. ACTIVITY: X EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) REQUIRED EVACUATION 6. OPERATION: COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER 8. CAUSE: X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL	it
AREA: AC LATITUDE: BLOCK: 772 LONGITUDE: COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER 6. ACTIVITY: X EXPLORATION(POE) DEVELOPMENT/PRODUCTION OTHER 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION REQUIRED EVACUATION BRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. OTHER 8. CAUSE: X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL	
RIG NAME: NOBLE GLOBETROTTER PIPELINE SEGMENT NO. OTHER 6. ACTIVITY: X EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION PIPELINE SEGMENT NO. OTHER SLIP/TRIP/FALL	
DEVELOPMENT/PRODUCTION OCCUPPOD) 7. TYPE: HISTORIC INJURY REQUIRED EVACUATION 8. CAUSE: EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL	
7. TYPE: HISTORIC INJURY REQUIRED EVACUATION EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL	
LTA (>3 days) RW/JT (1-3 days) RW/JT (>3 days) Other Injury LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER OTHER	
FATALITY 9. WATER DEPTH: 8807 FT.	
EXPLOSION 10. DISTANCE FROM SHORE: 188 MI.	
LWC HISTORIC BLOWOUT	
COLLISION HISTORIC >\$25K <=\$25K 13. SEA STATE: 4 FT.	

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R 01-MAY-2017

For Public Release

17. INVESTIGATION FINDINGS:

While in the process of running riser, the Gantry Crane Operator failed to move to the center of the drillship over the keel. As the gantry crane moved forward the spreader bar (utilized to transport the riser)came in contact with the Telescopic Man Basket pedestal located on the port side of the constuction floor. An "All Stop" was initiated and safety stand down meeting was conducted.

Crane Operator failed to ensure proper position of the riser joint in the centerline of the vessel over the keel prior to making any adjustments Forward or Aft with the riser joint.

Communication between the Flagger and Roustabouts(who was also spotting the load)did not provide the necessary effectiveness to prevent the Crane Operator from damaging equipment and losing control of the lifting equipment.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Crane Operator failed to ensure proper position of the riser joint in the centerline of the vessel over the keel prior to making any adjustments Forward or Aft with the riser joint.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Communication between the Flagger and Roustabouts(who was also spotting the load)did not provide the necessary effectiveness to prevent the Crane Operator from damaging equipment and losing control of the lifting equipment.

20. LIST THE ADDITIONAL INFORMATION:

None

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

MMS - FORM 2010 PAGE: 2 OF 3

For Public Release

ESTIMATED AMOUNT (TOTAL):

\$25,000

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

No recommendations at this time.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

Lessee failed to perform all operations in a safe and workmanlike manner while running riser with the gantry crane and spreader bar in the following ways:

- 1. The communication between the Flagger and Roustabouts(who was also spotting the load)did not provide the necessary effectiveness to prevent the Crane Operator from damaging equipment and losing control of the lifting equipment.
- 2. Crew members deviated from the established steps used to mitigate hazards of equipment damage while running riser with the gantry crane spreader bar while properly placing the riser in the saddle of the Catwalk Machine.
- 3. The Crane Operator failed to ensure proper position of the riser joint was in the centerline of the vessel over the keel prior to making any adjustment Forward or Aft with the riser joint.
- 25. DATE OF ONSITE INVESTIGATION:

20-MAR-2017

26. ONSITE TEAM MEMBERS:

James Holmes / David Kearns / Perry Brady / Casey Conklin /

29. ACCIDENT INVESTIGATION PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

Stephen P. Martinez

APPROVED

DATE: 20-APR-2017

MMS - FORM 2010 PAGE: 3 OF 3