

UNITED STATES DEPARTMENT OF THE INTERIOR  
MINERALS MANAGEMENT SERVICE  
GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1. OCCURRED

DATE: 06-JUN-2009 TIME: 2130 HOURS

2. OPERATOR: Repsol E&P USA Inc.  
REPRESENTATIVE: Feik, Courtney  
TELEPHONE: (281) 578-3388  
CONTRACTOR:  
REPRESENTATIVE:  
TELEPHONE:

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR  
ON SITE AT TIME OF INCIDENT:

4. LEASE: G28066  
AREA: GC LATITUDE:  
BLOCK: 304 LONGITUDE:

5. PLATFORM:  
RIG NAME: T.O. CAJUN EXPRESS

6. ACTIVITY:  EXPLORATION (POE)  
 DEVELOPMENT/PRODUCTION  
(DOCD/POD)

7. TYPE:  
 HISTORIC INJURY  
 REQUIRED EVACUATION  
 LTA (1-3 days)  
 LTA (>3 days)  
 RW/JT (1-3 days)  
 RW/JT (>3 days)  
 Other Injury

FATALITY  
 POLLUTION  
 FIRE  
 EXPLOSION

LWC  HISTORIC BLOWOUT  
 UNDERGROUND  
 SURFACE  
 DEVERTER  
 SURFACE EQUIPMENT FAILURE OR PROCEDURES

COLLISION  HISTORIC  >\$25K  <=\$25K

STRUCTURAL DAMAGE  
 CRANE  
 OTHER LIFTING DEVICE Pipe Handler  
 DAMAGED/DISABLED SAFETY SYS.  
 INCIDENT >\$25K  
 H2S/15MIN./20PPM  
 REQUIRED MUSTER  
 SHUTDOWN FROM GAS RELEASE  
 OTHER

6. OPERATION:

PRODUCTION  
 DRILLING  
 WORKOVER  
 COMPLETION  
 HELICOPTER  
 MOTOR VESSEL  
 PIPELINE SEGMENT NO.  
 OTHER

8. CAUSE:

EQUIPMENT FAILURE  
 HUMAN ERROR  
 EXTERNAL DAMAGE  
 SLIP/TRIP/FALL  
 WEATHER RELATED  
 LEAK  
 UPSET H2O TREATING  
 OVERBOARD DRILLING FLUID  
 OTHER One Spotter out of position

9. WATER DEPTH: 3868 FT.

10. DISTANCE FROM SHORE: MI.

11. WIND DIRECTION: WNW  
SPEED: 7 M.P.H.

12. CURRENT DIRECTION: SSE  
SPEED: 0 M.P.H.

13. SEA STATE: 1 FT.

17. INVESTIGATION FINDINGS:

Pipe handler operation: On 6-Jun-2009 at 2130 hours, the crane crews were in the process of moving one 13 5/8-inch casing joint from the port casing bay to the centerline casing bay using an electro-magnetic pipe handler (pipe handler). This was the 57th joint of casing to be moved by the pipe handler. Due to the deck configuration, the joint of casing had to be first landed in the catwalk machine in order to be correctly positioned to avoid contact with the drilling package during transfer, and it also had to be adjusted so that the pin end of the casing joint was forward in the bay. Markings were placed on the catwalk machine (pipe measurements were identified to be no longer than 45 feet) for the proper alignment to prevent contact with the drilling package. After the casing joint was adjusted in the catwalk, the pipe handler operator picked back up the load to move it to the centerline casing bay. As the joint was being moved to the centerline bay, the box end of the joint came into contact with the riser tensioner on the drilling package. This impact resulted in the joint of casing being knocked free from the pipe handler's magnets that were holding the joint of casing as it was being transferred toward the centerline bay. The load fell to the deck 12 feet from the pin end and 25 feet from the box end.

Investigation Findings: Prior to the start of the job, the pipe handler's travel path was barricaded, a Transocean THINK Plan was utilized and a Stop Work Authority was issued. There was, however, no discussion as to each of the two spotters responsibility during the job, and the two spotters involved in the job changed positions before this joint was to be moved. At the time of the incident, the spotter watching the pin end of the joint did not line up the spotting marks on the catwalk correctly, which contributed to the box end of the joint sticking out too far. The spotter watching the box end of the joint was in a position that did not allow him to see the travel path of the load. There were no injuries involved in the incident.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The joint of casing was sticking out further than it was intended, and one of the two spotters was not in the right position to see if the box end of the casing would clear the tensioner assembly.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

The second spotter did not line up the markings on the catwalk machine properly and both spotters changed positions before the 57th joint was to be moved. Also, there was no discussion as to each spotters responsibility during the job.

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

The property that was damaged was the box Threads end of one joint of 13 5/8-inch casing.

ESTIMATED AMOUNT (TOTAL): \$8,000

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:

Due to the specific nature of this incident, the Houma District has no recommendations to report to the Regional Office of Safety Management.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

N/A

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS:

Ben Coco / Casey Bisso /

29. ACCIDENT INVESTIGATION

PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Bryan A. Domangue

APPROVED

DATE: 10-FEB-2010

# INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE

INJURY

CONTRACTOR REPRESENTATIVE

FATALITY

OTHER \_\_\_\_\_

WITNESS

NAME:

HOME ADDRESS:

CITY:

STATE:

WORK PHONE:

TOTAL OFFSHORE EXPERIENCE:

YEARS

EMPLOYED BY:

BUSINESS ADDRESS:

CITY:

STATE:

ZIP CODE:

OPERATOR REPRESENTATIVE

INJURY

CONTRACTOR REPRESENTATIVE

FATALITY

OTHER \_\_\_\_\_

WITNESS

NAME:

HOME ADDRESS:

CITY:

STATE:

WORK PHONE:

TOTAL OFFSHORE EXPERIENCE:

YEARS

EMPLOYED BY:

BUSINESS ADDRESS:

CITY:

STATE:

ZIP CODE:

# INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE

INJURY

CONTRACTOR REPRESENTATIVE

FATALITY

OTHER \_\_\_\_\_

WITNESS

NAME:

HOME ADDRESS:

CITY:

STATE:

WORK PHONE:

TOTAL OFFSHORE EXPERIENCE:

YEARS

EMPLOYED BY:

BUSINESS ADDRESS:

CITY:

STATE:

ZIP CODE:

