# The Case History of an Underground Flow Offshore Texas

An Interactive Group Learning Exercise

Developed by John Rogers Smith, P.E., Ph.D. Louisiana State University

Funded by Minerals Management Service U.S. Department of the Interior

# The Case History of an Underground Flow Offshore Texas

An Interactive Group Learning Exercise

Developed by

John Rogers Smith, P.E., Ph.D. Louisiana State University

Funded by


Minerals Management Service U.S. Department of the Interior

### **Overview**

•


•


- Begins during platform development drilling during 1980's
- The real beginning a few months earlier
- Focus on "Turning Points"



# Mudlog 6th Well

Ē





## **Unanticipated Pressure**

Kill wt. mud = mud wt. + (SIDPP/(.052 x TVD)) = 9.8 + (600/(.052 x 8710')) =

Drill pipe stuck

•

•


•


•

- Required 13.6 ppg mud to stop flow
- Cemented drillstring in hole

Mudlogs 5th Well

Ē





6th Well

# **Unanticipated Pressure**

Moved well location

.

•


•

•

- Took kick 30' shallower in same drilling break; shut in immediately; 3 bbl. gain
  - Kill wt. mud = 12.6 + (800 psi/(.052 x 8680')) = 14.4 ppg

(Note: Pressure at shoe exceeds the fracture pressure)

- Pipe stuck while working it through the Hydril
- Killed well with 14.4 ppg
  - Cemented drillstring in well to plug back



### What's Wrong Here?

### **Geologic Possibilities**

- Pressures higher in section due to being in different fault block
- Pressures shallower than offsets due to missing stratigraphic section

Neither geologic possibility was supported by either geological or geophysical data

### Man Made Possibilities

- Pressure transfer in offset well
- 5th well was one of the following:
  - · closest offset
  - · had seen this section normally pressured
  - · had a major well control problem deeper

# Reaction


- Establish ad hoc, multi-disciplinary team including division operations manager and assigned essentially full time to this problem
  - Drilling Engineers
  - Drilling Supervisors
  - Production Engineers
  - Log Analysts
- · Re- enter 5th well
- Clean out to TD
- Run logs:
  - temperature
  - noise

•

- · cement bond
- · pulsed neutron
- Check annulus pressures


# **Temperature Log** Before

Ē



# Noise Log Before

Ē



# **Cement Bond Log**


# "Free Pipe" From 11900'


(170' Below 9 5/8" Shoe) To 14100'


# How Did We Get In This Shape?


Ē


Let's review the "Well Control Problem" in the 5th well


























### **Confirming Recovery**

- 1. No flow from well
- 2. Cement tested to +3000 psi
- Dressed off liner top cement and tested to +3200 psi for 30 min.
- 4. Test liner top with water cushion in stages to -2300 psi ~14.5 ppg EMW for one hour
- 5. Ran liner tieback

#### *Turning point :*

No attempt to confirm that probable (in hindsight) underground flow had been stopped or that pressure source on  $11 \frac{3}{4}$ " x 9 5/8" annulus was shut off.

### Recovery

Now we are back to where we started the review:

# What are we going to to do to stop the apparent on-going underground flow?


## Kill it?


or


Bridge it?

### Can we kill it?


### Flowing Bottom Hole Pressures For Dynamic Kill








### **Temperature Log** Before vs. After




## Noise Log Before

Ē



After



### **Cement Bond Log**

### Before

- "Free Pipe" from 11900'
- · (170' Below 9 5/8" Shoe) To 14100'

### After

- Cement with some bonding to both pipe and formation from 13200' to 14100' (Throughout major gas sand)
- 20' cement seal at top of gas sand (where multiple "Squeezes" were performed)
- Some additional cement up to 12950' (Confirmed with tracer)

Phase	Critical Issue
Planning	Risk of lost circulation with tight clearances not mitigated
Avoidance	No record of displacements
Detection	Poor, hole not kept full
Reaction	Good, shut-in when flow seen
Control	Poor, squeeze plan not followed, Driller's method improperly applied
Original "Kill":	
Loss of Control	Not identified
Recovery	None – only isolated
Confirmation	None
Second Kill:	
Loss of Control	Inferred by kicks, logs confirmed
Second Recovery	Planned, evaluated after each step
Confirmation	With comparison to baseline logs

Ē