## **Civil Penalties Program**

The goal of the BSEE OCS Civil Penalties Program is to ensure safe and environmentally sound operations on the Outer Continental Shelf. Through the pursuit, assessment, and collection of civil penalties the program is designed to encourage compliance with the Outer Continental Shelf Lands Act (OCSLA) and BSEE's implementing regulations.

## 2014 Civil Penalties Summary Penalties Paid through the Calendar Year of 2014

(1/1/2014 - 12/31/2014)

Name of Violator and Case No.	Violation and Date(s)	Penalty Paid and Date Paid	Regulation(s) Violated 30 CFR)
Linder Oil Company (Production Services Network) G-2009-001	During the course of a BSEE inspection the shutdown valve (SDV), for the fuel gas to the main generator, was bypassed. It was also discovered that Linder was discharging produced water from the production separator into the containment skid. Oct. 25- Oct. 28, 2008 Oct. 2 – Oct. 28, 2008	\$150,000* 6/20/14 12/24/14 *Note: Represents partial payments pursuant to a Settlement Agreement that also addressed Linder's decommissi oning obligations. Linder owed a total penalty of \$500,000. Linder has now paid a total of \$500,000.	250.803 250.803(a)
McMoran Oil & Gas LLC G-2011-007	During a BSEE incident investigation, it was discovered that McMoran failed to move equipment containing hydrocarbons at least 35 feet from welding area. Another violation was the explosion and rupture of two oil tanks which resulted in spilled oil into the Gulf of Mexico.	\$60,000 11/25/14	250.300(a) 250.113

	May 21, 2010 (2		
	violations)		
McMoran Oil & Gas LLC	During a BSEE incident investigation, it was	\$35,000 12/5/14	
G-2012-007	discovered that a tubing hanger pin ejected while attempting to separate well head from well bore causing an injury.	12/3/14	
	Oct. 27, 2011		250.107(a)
Anadarko	During a BSEE incident	\$70,000	
Petroleum Corporation	investigation, it was discovered that	10/10/14	
(Ensco Offshore Co.)	Anardarko failed to develop and use a management system for operation of the subsea		
G-2012-030	BOP system, which includes procedures for prevention of accidental or unplanned disconnects of the system. It was also found that the driller's energized BOP panel was accessed with ongoing wireline operations in the well bore. No JSA had been developed and no Permit to Work had been issued because appropriate personnel were not aware of the action. Dec. 8, 2011 - Feb.19, 2012		250.401
	Feb. 19, 2012		250.442
Apache Corporation	During the course of a BSEE investigation, it was discovered that the	\$40,000 9/26/14	
G-2012-038	swing brake on the crane was inoperative at the time of the incident. None of the individuals involved in the operation, with the exception of the crane operator, had knowledge of this deficiency. This deficiency was not covered in the JSA. Furthermore, the		
	individuals interviewed		250.107

	1	,	
	admitted to not wearing gloves during the operation, despite the wearing of gloves being cited in the JSA.		
	August 12, 2012		
Fairways Offshore Exploration, Inc.	BSEE inspection, the SCSSV for Well A-2 and A-2D was being utilized	\$40,000 5/6/2014	
Àssociates, LLC) G-2013-010	as a tubing plug. The tubing plug had not been tested for leakage at the		
	required 6 month interval.		
	Feb 1 – Oct 24, 2012		250.804(a)(1)
Energy Resource Technology GOM, Inc.	During the course of an unannounced BSEE inspection, it was discovered that the	\$30,000 8/25/14	
G-2013-017	operator failed to shut-in all wells while performing Hot-work cutting operations within the Well-Bay. ERT failed to perform operations in a safe and workmanlike manner.		
	November 26, 2012		250.107
Mariner Energy Resources, Inc.	During a BSEE incident investigation, multiple violations were	\$295,000 11/12/14	
G-2013-021	discovered that led to an overpressure event in production vessels that caused a fire. Sept. 2, 2010 (8 violations)		250.107 250.107(a) 250.803(c) 250.803(b)(8) 250.300(a)
Energy Resource	During the course of a	\$80,000	250.300(a)
Technology GOM, Inc.	BSEE investigation, it was determined that a crane lifting operation led to the collapse of the	3/12/14	
Production Services)	crane boom, causing a fatality.		
G-2013-022	August 16, 2011 (2 violations)		250.401(e)
Ensco Offshore Co.	During a BSEE incident investigation, it was discovered that Ensco	\$70,000 12/2/14	250.442
	uiscovered that Ensco	, _, 1 1	250.401(e)

G-2013-025	failed to develop and use a management system for operation of the subsea BOP system, which includes procedures for prevention of accidental or unplanned disconnects of the system. It was also found that the driller's energized BOP panel was accessed with ongoing wireline operations in the well bore. No JSA had been developed and no Permit to Work had been issued because appropriate personnel were not aware of the action. Feb. 19, 2012 Dec. 9, 2011 – Feb. 19, 2012		
McMoRan Oil & Gas LLC (Danos & Curole Marine Contractors, Inc.) G-2013-028	During the course of a BSEE Investigation into an incident with injury, it was discovered that McMoRan failed to adhere to safety policies and perform all operations in a safe and workmanlike manner during riser pipe decommissioning operations. They did not having proper management and onsite supervision to address safety hazards and deficiencies that contributed to the cause of the incident. March 30, 2013	\$35,000 9/28/14	250.107(a)(1)
Stone Energy Corporation G-2013-029	During an inspection, it was discovered that Stone Energy did not comply with blowout prevention equipment requirements during the well abandonment operation. The well was not in a Temporarily	\$50,000 8/6/14	250.170(c)(1) 250.1706(c)(5)

	Abandoned (T&A'd) status at the time of the inspection. This means that communication still existed between the hydrocarbon bearing zone and the wellbore. The kill line not being connected as required posed a threat to personnel and the facility in the event of a well control situation.		
	March 26, 2013 (2		
Black Elk Energy Offshore Operations, LLC 2013-030	violations) During the course of a BSEE inspection, it was discovered that the Sump Tank LSH selector valve was in the bypass position, it was not flagged, nor was it being monitored. The Sump Tank is the containment system for deck drainage from all production vessel skids. Due to the safety device being in the bypass mode, the LSH would not have been able to perform its design function and shut in the facility in the event of a high level in the Sump Tank.	\$30,000 4/9/14	
	March 11, 2013		250.803(c)
GOM Shelf LLC G-2013-032	During an inspection, several violations were discovered. Inspectors found that a test separator had been placed out of service on the instrument panel. When inspectors questioned why the vessel was out of service, they found that it had been placed out of service because it was full of sand. Inspectors returned to the structure a day later, performed a re-	\$1,230,000 11/12/14	
	test and audited the		250.802(b) 250.107(a)(1)

Danos and Curole Marine Contractors, Inc. G-2013-034	contributed to the cause of the incident. March 30, 2013 During the course of a BSEE investigation, it was determined D&C failed to operate in a safe and workmanlike manner for not following their Safe Work Practice Procedures and policies, including failure to utilize Stop Work Authority,	\$30,000 7/30/14	250.107(a)
(Danos & Curole Marine Contractors, Inc.) G-2013-033	operations in a safe and workmanlike manner during riser pipe decommissioning operations. They did not having proper management and supervision to address safety hazards and deficiencies that contributed to the cause	8/6/14	
Arena Offshore, LP	records. Records showed that GOM Shelf was aware of sand entering the production system for a prolonged period of time. Despite this awareness, GOM Shelf failed to take steps to sufficiently address the sand hazards. This failure placed the safety of people on the facility, as well as the environment, at risk. March 12, 2013 Feb. 1 – March 12, 2013 During the course of a BSEE investigation, it	\$35,000	

Chevron U.S.A. Inc. G-2013-035	planning, and make operational errors contributed to the cause of the injury. March 30, 2013 During the course of a BSEE investigation, it was discovered that the operator failed to operate in a safe and workmanlike manner by failure to utilize proper	\$35,000 9/23/14	
	personal protective equipment per the "Corrosive Chemical Procedure" while dismantling the pump assembly. In addition, there was not a Material Safety Data Sheet for the chemical located on the facility nor was there a Job Safety Analysis or permit to work prepared with this job task. Finally, there was no eye wash station(s) located near the temporary chemical pumping area.		
Black Elk Energy	May 21, 2013 During an onsite BSEE	\$70,000	250.107(a)(1)
Offshore Operations, LLC G-2013-036	investigation, there was a pollution incident that involved a gasket failure on the departing pipeline riser resulting in the release of liquid hydrocarbons into Gulf of Mexico waters. Also, the facility had been shut-in prior to Black Elk receiving a Performance Improvement Plan (PIP) notification letter from the BSEE Regional Director which states in part: 1) Keep all facilities that currently are in a shut-in status in such status until it provides BSEE with documentation of the corrective actions taken	4/9/2014	250.101
	to safely return each		250.107(a)

operations in accordance with lease stipulations as noted in excerpts number 1&2 above from the November 21, 2012 PIP notification letter.Mariner Energy, Inc.During the course of a BSEE inspection, 3 violations were discovered where operations were not being conducted in a safe and workmanlike manner. Violation 1 involved unsecured and improperly assembled scaffolding/fabricated platform utilized for the decommissioning operations. BSEE inspectors observed that the scaffolding/fabricated platform and was missing some of the bracings and pins. This could have allowed the scaffolding to shift while personnel were working from the scaffolding deck. Violation No. 2 involved an open-hole/fall hazard located on the deck scaffolding. This hazard posed a potential threat of personnel falling onto the lower platform deck or into the Gulf of Mexico			facility into operational status to BSEE's satisfaction. 2) Notify the appropriate District Office at least 48 hours prior to returning these facilities to production to allow for the proper BSEE inspection. Black Elk	
Violations)Mariner Energy, Inc.During the course of a BSEE inspection, 3 violations were\$280,000G-2013-037discovered where operations were not being conducted in a safe and workmanlike manner. Violation 1 involved unsecured and improperly assembled scaffolding/ fabricated platform utilized for the decommissioning operations. BSEE inspectors observed that the scaffolding/fabricated platform was not secured to the platform and was missing some of the bracings and pins. This could have allowed the scaffolding to shift while personnel were working from the scaffolding deck. Violation No. 2 involved 			with lease stipulations as noted in excerpts number 1&2 above from the November 21, 2012 PIP notification letter.	
Mariner Energy, Inc.During the course of a BSEE inspection, 3 violations were discovered where operations were not being conducted in a safe and workmanlike manner. Violation 1 involved unsecured and improperly assembled scaffolding/ fabricated platform utilized for the 				
G-2013-037 discovered where operations were not being conducted in a safe and workmanlike manner. Violation 1 involved unsecured and improperly assembled scaffolding/ fabricated platform utilized for the decommissioning operations. BSEE inspectors observed that the scaffolding/fabricated platform was not secured to the platform and was missing some of the bracings and pins. This could have allowed the scaffolding to shift while personnel were working from the scaffolding deck. Violation No. 2 involved an open-hole/fall hazard located on the deck scaffolding. This hazard posed a potential threat of personnel falling onto the lower platform deck or into the Gulf of Mexico			During the course of a BSEE inspection, 3	
of the scaffolding. Violation No. 3) also 250.107(a	(a)	250 107(	discovered where operations were not being conducted in a safe and workmanlike manner. Violation 1 involved unsecured and improperly assembled scaffolding/ fabricated platform utilized for the decommissioning operations. BSEE inspectors observed that the scaffolding/fabricated platform was not secured to the platform and was missing some of the bracings and pins. This could have allowed the scaffolding to shift while personnel were working from the scaffolding deck. Violation No. 2 involved an open-hole/fall hazard located on the deck scaffolding. This hazard posed a potential threat of personnel falling onto the lower platform deck or into the Gulf of Mexico waters from the decking of the scaffolding.	G-2013-037

		-	
	hole/fall hazard located on the platform lower deck. BSEE inspectors observed personnel working on a section of the platform deck that had no hand rails presenting a threat of personnel falling into the Gulf of Mexico Waters.		
Apache Corporation	During a BSEE incident investigation, it was discovered that the rigger	\$75,000 11/12/14	
G-2013-038	on top of Marine Portable Transfer tank unhooked the D-ring and then dropped it over the side of tank. The D-ring caught the right index finger of the employee between the side of the tank and the D-ring. It was initially stated that the rigger was wearing the company required high-visibility, impact resistant gloves, but later into the investigation changed his testimony to say he was not wearing any gloves at the time of the incident.		
	April 11, 2013		250.107(a)(1)
Linder Oil Company G-2013-039	During a BSEE inspection of the facility's plug and abandonment operations, the inspector found an open hole that was un- barricaded on one side and accessible to personnel working on the well deck creating a fall hazard. After further review of documents, it was found that after pulling the drive pipe from the well B1, an approximately 34" diameter hole was created in the grating in	6/20/14	
	the well deck area.		250.107(a)(1)

	May 16, 2013		
Black Elk Energy Offshore Operations, LLC 2013-040	During the course of a BSEE investigation into an incident with injury, the investigators discovered 2 violations of failing to conduct operations in a safe and workmanlike	\$75,000 4/28/14	
	manner.		
	May 4, 2013		250.107(a)(1)
BP Exploration & Production Inc.	During the incident investigation, two violations were found.	\$65,000 11/14/14	
G-2013-041	One was for discharging pollutants into Gulf waters and the other was for failure to maintain equipment in a safe manner which led to the discharge.		
	April 19, 2013 (2 violations)		250.107 250.300(a)
W&T Offshore, Inc.	During the course of a BSEE inspection, it was	\$30,000	
G-2013-043	discovered that the LSL for the Oil Treater was operating in the by-pass position, and was not flagged or monitored by personnel.	4/24/14	
	June 7, 2013		250.803(c)
Hercules Offshore	During the course of a BSEE investigation on a	\$25,000	
G-2013-045	drilling rig, it was determined that the air hoist cable had become entangled with the hose safety clamp during the replacement of inner bushings. The bushing puller tool and air hoist hook were secured to an anchor post after the bushings were replaced. It was also observed that the driller's view of the entangled air hoist cable was obstructed by the traveling block and top	3/25/14	
	drive. The downward		250.107(a)

force of the traveling block and top drive put an undetermined amount of force on the cable and anchor post, breaking the post from the rig floor allowing either the anchor post or the bushing puller tool to strike the injured party.		
July 8, 2013		
During the course of a BSEE investigation	\$45,000	
into pollution incident, it was discovered that LSH for the Flash Tank (MBB-150) was in bypass and not flagged and monitored resulting in the operator's failure to prevent unauthorized discharge of pollutants into offshore waters.	8/4/14	
February 27, 2013 March 2, 2013		250.803 250.107(a)
During the incident investigation, it was found that a person was injured when a flash fire occurred while employees were conducting an acidizing operation on the float cell. The flash fire resulted in a contract employee suffering first and second degree burns on his right arm and torso.	\$40,000 8/25/14	
July 20, 2013		250.107(a)
During a BSEE on-site inspection, multiple violations were found. Personnel were working in unsafe areas of the platform; there was unsecured and improperly assembled scaffolding; missing handrails on the platform	\$84,000 10/3/14	250.107(a)
	block and top drive put an undetermined amount of force on the cable and anchor post, breaking the post from the rig floor allowing either the anchor post or the bushing puller tool to strike the injured party. July 8, 2013 During the course of a BSEE investigation into pollution incident, it was discovered that LSH for the Flash Tank (MBB-150) was in bypass and not flagged and monitored resulting in the operator's failure to prevent unauthorized discharge of pollutants into offshore waters. February 27, 2013 March 2, 2013 During the incident investigation, it was found that a person was injured when a flash fire occurred while employees were conducting an acidizing operation on the float cell. The flash fire resulted in a contract employee suffering first and second degree burns on his right arm and torso. July 20, 2013 During a BSEE on-site inspection, multiple violations were found. Personnel were working in unsafe areas of the platform; there was unsecured and improperly assembled scaffolding; missing	block and top drive put an undetermined amount of force on the cable and anchor post, breaking the post from the rig floor allowing either the anchor post or the bushing puller tool to strike the injured party. July 8, 2013 During the course of a BSEE investigation into pollution incident, it was discovered that LSH for the Flash Tank (MBB-150) was in bypass and not flagged and monitored resulting in the operator's failure to prevent unauthorized discharge of pollutants into offshore waters. February 27, 2013 March 2, 2013 During the incident investigation, it was found that a person was injured when a flash fire occurred while employees were conducting an acidizing operation on the float cell. The flash fire resulted in a contract employee suffering first and second degree burns on his right arm and torso. July 20, 2013 During a BSEE on-site inspection, multiple violations were found. Personnel were working in unsafe areas of the platform; there was unsecured and improperly assembled scaffolding; missing handrails on the platform

	existing handrails.		
	May 24-28, 2013		
Apache Corporation G-2013-049	During the course of a BSEE onsite inspection, it was discovered that the fire and gas detection system for several portable buildings were found with the power switch in the off position rendering the system inoperable and disabling the backup battery system, leaving the building without adequate fire detection.	\$360,000 9/4/14	
	June 24-27, 2013 (4 violations)		250.803(b)(9)(v)
Nexen Petroleum U.S.A. Inc. G-2013-051	During the course of an inspection, BSEE Inspectors discovered the SCSSV for wells I-1 and I-2 operating in the by-pass position. Also, they were not flagged or monitored by personnel.	\$40,000 8/30/14	
	September 13, 2013 (2 violations)		250.107(a)
Energy XXI GOM, LLC G-2013-052	During a BSEE onsite inspection, inspectors observed multiple oil- leaks on the gas compressor. During a follow up inspection, the operator failed to correct multiple oil leaks on the gas compressor.	\$7,248 3/5/14	
	July 30-September 17, 2013		250.107
Dynamic Offshore Resources, LLC G-2013-053	During the incident investigation, it was found that on several occasions the rig crew made the decision to continue to pull drill pipe out of the wellbore even while they were taking gains through the trip tank.	\$125,000 10/7/14	
			250.456(a)

	May 6 – June 6, 2013		
Nexen Petroleum U.S.A. Inc.	During the course of a BSEE inspection, inspectors discovered	\$20,000 9/26/14	
G-2013-055	that the helicoptor landing deck was being utilized as an extension of the platform to conduct abandonment operations without the addition of hand rails.		
	September 24, 2013		250.107(a)
SandRidge Energy	During an inspection, gas was observed escaping from a vent cover of a wet	\$250,000 11/14/14	
G-2013-056	oil tank, into the atmosphere, without flame arrestor protection.		
	Sept. 30 - Oct. 9, 2013		250.107
Fairways Offshore		\$32,250	
Exploration	discovered a violation in which the operator was unable to provide	10/3/14	
G-2014-002	testing records for the Well JA-2D SCSSV, being utilized as a tubing plug. In addition, the operator failed to correct a previous violation for failure to conduct required daily pollution inspections.		
	Sept. 30, 2011 – Aug. 29, 2013 Dec. 7, 2012 – Aug.29, 2013		259.301 250.804(a)(1)(i)
McMoran Oil and Gas LLC	An inspection was conducted because an oil	\$85,000	
G-2014-004	sheen was spotted during flight. Violations connected to the spill were due to the sump pile not operating automatically; the LSH and sum pile pneumatic pump failed, and then the sump pile was used as a processing device.	11/13/14	
	October 24, 2013 (3 violations)		250.300(b)(4) 250.802(b) 250.300(a)

Exploration New Orleans, LLC in G-2014-005 G g g ir p m C W&T Offshore, Inc. f G-2014-006 P M tr f G-2014-006 M tr f S G-2014-006 M M tr f S G A Black Elk Energy D	During the course of a SEE onsite hspection, it was liscovered that the Coiled Tubing Unit reel lear and chain luards/covers were not hstalled to protect hersonnel from the hoving components.	\$20,000 10/20/14	
Orleans, LLC ir d G-2014-005 G W&T Offshore, Inc. G-2014-006 M tr fu ir S Ic o W M T S A Black Elk Energy	nspection, it was liscovered that the Coiled Tubing Unit reel lear and chain luards/covers were not installed to protect lersonnel from the noving components.	10/20/14	
G-2014-005 G-2014-005 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-006 G-2014-005 G-2014-006 G-2006 G-2014-006 G-20	liscovered that the Coiled Tubing Unit reel lear and chain luards/covers were not installed to protect personnel from the noving components.		
g g ir p m G-2014-006	ear and chain uards/covers were not nstalled to protect ersonnel from the noving components. October 29, 2013		
G-2014-006 W&T Offshore, D Inc. W G-2014-006 W th fu ir S Ic o W th fu fu fu fu fu fu fu fu fu fu fu fu fu	uards/covers were not nstalled to protect ersonnel from the noving components. October 29, 2013		
ir pm m C W&T Offshore, Inc. G-2014-006 P W th fu ir S Ic o w w it p Black Elk Energy	nstalled to protect ersonnel from the noving components. October 29, 2013		
Pm W&T Offshore, D Inc. W G-2014-006 P W th fu ir S Ic o W M H A Black Elk Energy D	ersonnel from the noving components. October 29, 2013		
M&T Offshore, D Inc. W G-2014-006 P W th fu ir S Ic o w it p Black Elk Energy D	noving components. October 29, 2013		
W&T Offshore, D   Inc. W   G-2014-006 P   W ft   ft ft	October 29, 2013		
W&T Offshore, D Inc. w G-2014-006 P W th fu ir S Ic o w it p A Black Elk Energy D			
Inc. w G-2014-006 P W th fu ir S IC o w it P A Black Elk Energy D			250.107
G-2014-006 P W th fu ir S IC o w it P A Black Elk Energy D	Ouring an inspection, it	\$60,000	
G-2014-006 P W ft f S Ic o w it p A Black Elk Energy D	vas discovered that a	11/10/14	
W th fu ir S Ic o w it P A Black Elk Energy	usible cap had been laced on the SSV (of		
th fu ir S lc o w it p A Black Elk Energy D	Vell G-9) during testing		
ir S Ic o w it p A Black Elk Energy D	ne previous day. The		
S Ic o w it p A Black Elk Energy D	usible cap had been left		
lc o w it p A Black Elk Energy D	n place rendering the SSV inoperable and		
o w it p A Black Elk Energy D	ocking the valve in the		
it p A Black Elk Energy D	pen position. The SSV		
P A Black Elk Energy	vas not flagged, nor was		
A Black Elk Energy	being monitored by		
Black Elk Energy D	ersonnel		
	Nug. 7 – 8, 2014		250.803(c)
Offeboro	Ouring an onsite	\$180,000	
	spection BSEE issued	4/28/14	
	hree INCs (one for each	4/20/14	
	vell that was flowing at ne time the bypassed		
	elay was found.) BSEE		
	nspectors performed a		
	unction test of the		
	mergency ESD system		
	while the relay was in hypass, to see if the		
	SCSSV's pressure would		
	leed off. During this		
fu	unction test, the		
	CSSV's control pressure		
d	lid not bleed off.		
A	vpril 29, 2013 (3		
	iolations)		250.803(c)
			250.803
		\$25,000	
		7/6/14	
		1 · · · · · · · · · · · · · · · · · · ·	
	in incident with injury,		
0			
Inc. B	Ouring the course of a SEE investigation into	\$25,000 7/6/14	230.003

	1		
	construction worker was injured while stepping on grating that was secured with plastic zip ties.		
	December 9, 2013		
Hilcorp Energy GOM, LLC	During a BSEE onsite inspection, three INCs were issued and	\$75,000 8/14/14	
G-2014-013	forwarded for civil penalty review. An inspector discovered a LSL on the L.P. Separator was in bypass mode, and the separator win in operation and not being tested or maintained. Another violation discovered was that the bottom isolation valve for the LSH on the sump was in the closed position. The sump was not being tested or maintained. The third violation discovered was a valve on the air supply for the sump pump was in the closed position preventing its ability to automatically operate.		
	May 24, 2012 (3 violations)		250.803(c) 250.300(b)
<b>Chevron U.S.A.</b> Inc. G-2014-015	During the course of an inspection, BSEE Inspectors discovered an open hole next to the Lease Automatic Custody Transfer skid. The hole was not properly barricaded to prevent personnel from entering	\$160,000 7/30/2014	
	the hazardous area. September 1-9, 2013		250.107
Anadarko Petroleum Corporation G-2014-017	During the course of a BSEE investigation involving injuries, it was discovered that a composite air pressure vessel exploded causing	\$37,000 9/23/14	200.101
	a large fireball and flying shrapnel, followed by a venting sound. The		250.107(a)

	Subsea personnel were injured, receiving second and third degree burns from the flash fire.		
	November 2, 2013		
SandRidge Offshore, LLC (Wood Group Production Services)	During the course of a BSEE investigation involving injuries, it was discovered that an employee was attempting to clear a line that was being used to transfer	\$35,000 9/8/14	
G-2014-019	coolant (antifreeze) from a 500 gallon poly tank to a compressor. The poly tank exploded and severely injured employee's hand.		250.107(a)
Fairfield Nodal	During the course of a	\$430,000	
G-2014-023	BSEE field investigation, Fairfield failed to follow an approved plan that led	12/17/14	
	to the fatality of Spotted Dolphin by entanglement of the tethered line on the Dolphin.		
	November 7, 2013 – January 24, 2014 (2 violations)		250.551.3 250.551.6(a)(2)
Tana Exploration Company, LLC	During the time of the inspection, BSEE	\$25,000	
G-2014-025	Inspectors discovered that the well abandonment operations with the tree removed did not contain a secondary power source, independent from the primary source, with sufficient capacity to close all BOP stack components and hold them closed. BSEE Inspectors discovered the pneumatic supply line connected to the pneumatic driven secondary pump on the Hydraulic Power Unit having its "Air Pump Shut-off Valve" in the closed or blocked	12/24/14	250.1706
	CIOSED OF DIOCKED		200.1700

	position.		
	April 18, 2014		
<b>EPL Oil and Gas, Inc.</b> (Spartan Offshore Drilling, LLC) G-2014-029	During the course of a BSEE investigation into an incident with injury, the investigators discovered that an employee was injured while preparing the Texas Deck to install the pollution pan around the BOP on the drilling rig. The section of grating was not secured at the time of the incident.	\$37,000 11/13/14	
	December 17, 2013		250.107(a)
Cochon Properties, LLC G-2014-030	During an inspection, it was discovered that the gas detection system in the temporary living quarters was inoperable. The power switch to the gas detection-monitoring unit was in the off position.	\$20,000 11/19/14	
	May 27, 2014		250.107(a)
EnVen Energy Ventures, LLC G-2014-031	During a BSEE inspection, upon review of the SCSSV inspection records, the inspectors discovered that the leakage rate for the SCSSVs used in lieu of a tubing plug, in two wells, was above the maximum allowable set forth in the regulations. Nov. 10, 2013 – Feb. 12, 2014 Nov. 10, 2013 – Mar. 15, 2014	\$438,000 11/21/14	250.804(a)(1)(i) 250.804(a)(1)(i)
Beta Operating	During the course of a	\$25,000	
<b>Company, LLC</b> P-2013-002	BSEE investigation into an incident with injury, the investigators discovered that an injured party received an electric shock of an estimated 98,000 volts at very low amperage. The person was not wearing proper	4/7/14	250.107

	personal protective equipment as required by the JSA at the time of the incident.		
Exxon Mobil Corporation P-2013-003	During the course of a BSEE investigation into an incident with injury, the investigators discovered	\$30,000 4/30/14	
	that an employee fell off the dragway onto the drill deck.		
	September 18, 2012		250.107(a)
Exxon Mobil Corporation	During the course of a BSEE investigation, it was discovered that a	\$20,000 9/12/14	
P-2014-001	release of H2S gas under high pressure occurred due to maintenance of an incorrect injection gas compressor fitting. A maintenance team commenced work on the wrong fitting which led to a blowout.		
	January 19, 2013		250.107
Beta Operating Company, LLC P-2014-005	During the course of a BSEE investigation, it was discovered that crude oil was released	\$30,000 12/15/14	
	through the flare boom. A safety device was bypassed for reasons other than startup, maintenance or testing and was not properly flagged or monitored.		
	May 23, 2014		250.803(c)
Т	otal Penalties Paid: 1/1/20	014 - 12/31/201	4
	<b>53 Cases:</b> \$5,69	5,498	

The purpose of publishing this civil penalties summary is to provide information to the public regarding OCSLA and regulatory violations of special concern in OCS operations and to provide an additional incentive for safe and environmentally sound operations.

ESD	Emergency Shut Down
INC	Incident of Non Compliance
JSA	Job Safety Analysis

LSH	Level Safety High
LSL	Level Safety Low
SCSSV	Surface Controlled Subsurface Safety Valve
SDV	Shut Down Valve
SSV	Subsurface Safety Valve