UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

1.	H	TRUCTURAL DAMAGE
	DATE: 21 CON 2023 111111 0020 1100ND 11	RANE
2.	OPERATOR: Shell Offshore Inc. REPRESENTATIVE: TELEPHONE: CONTRACTOR: REPRESENTATIVE: SI	THER LIFTING AMAGED/DISABLED SAFETY SYS. NCIDENT >\$25K ESP-A VFD Damaged 2S/15MIN./20PPM EQUIRED MUSTER HUTDOWN FROM GAS RELEASE THER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR	8. OPERATION:
	ON SITE AT TIME OF INCIDENT:	x PRODUCTION
4.	LEASE: G17565 AREA: AC LATITUDE: BLOCK: 857 LONGITUDE:	DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
5.	PLATFORM: A(Perdido)	DECOMMISSIONING
	RIG NAME:	☐ PA ☐ PIPELINE ☐ SITE CLEARANCE
6.	ACTIVITY: EXPLORATION (POE) DEVELOPMENT/PRODUCTION	TA PLATFORM OTHER
7.	(DOCD/POD) TYPE:	9. CAUSE:
	INJURIES: HISTORIC INJURY OPERATOR CONTRACTOR REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days) RW/JT (1-3 days) RW/JT (>3 days)	EQUIPMENT FAILURE HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
	FATALITY Other Injury	10. WATER DEPTH: 7835 FT.
	Other Injury	11. DISTANCE FROM SHORE: 140 MI.
	POLLUTION X FIRE EXPLOSION	12. WIND DIRECTION: SPEED: M.P.H.
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER	13. CURRENT DIRECTION: SPEED: M.P.H. 14. SEA STATE: FT.
	SURFACE EQUIPMENT FAILURE OR PROCEDURES	15. PICTURES TAKEN:
	COLLISION	

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R 16-AUG-2023

For Public Release

On June 21, 2023, at 0930 hours, Shell Offshore Inc. (Shell) reported a fire occurred at Alaminos Canyon (AC) 857, Perdido Spar, lease G-17565. The Variable Frequency Device A (VFD-A) failed releasing smoke and setting off smoke detectors in the Subsea Motor Control Center room (Subsea MCC), this caused an automated facility shut-in and personnel muster. The estimated cost of replacement is \$65,000.00, there were no injuries or pollution reported with this incident.

On June 22, 2023, the Bureau of Safety and Environmental Enforcement (BSEE) Lake Jackson District Well Operations Accident Investigator and Production Lead Inspector conducted an onsite investigation at AC 857 Perdido Spar. They collected documentation, maintenance records, alarm logs and one-line drawings of the effected circuit and photographs were taken.

The Shell investigation concluded the failure was due to the to the B-phase on the reactor of the VFD-A had failed to ground. The reactor failure, released smoke, this resulted with smoke activating smoke detectors in the Subsea MCC room, the automated system shut-in the facility as designed. Facility personnel mustered, as the Shell Fire Team was sent to the Subsea MCC room. Smoke was evident in the room, but there was no visible evidence of charring, and the Fire Team did not extinguish any fires. Electrician was dispatched to the MCC room to begin surveying the control cabinets, no notable temperature difference on outside of the cabinets. Offshore Installation Manager (OIM) gave permission to open cabinets, for further survey, cabinet A had a temperature of 350 F (Fahrenheit), and cabinets B, C and D cabinets 210 F was observed. The Electrician then isolated, locked, and tagged out cabinet A from the power source and taken out of service, so that remaining equipment could be returned to service. A Fire watch was established at the MCC room, and the community was allowed to leave the muster, but not allowed to return to work. BSEE Investigators agree with Shell Offshores' conclusions, that the fire was due to the failure of the B-phase reactor of the VFD-A to ground, causing smoke to be released and setting off smoke detectors.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Failure of the Variable Frequency Device-A.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

None

20. LIST THE ADDITIONAL INFORMATION:

None

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Variable Frequency Device-A

Fire Damage

ESTIMATED AMOUNT (TOTAL): \$65,000

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Siemens to investigate why the reactor thermal switch did not trip the drive on over temperature.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

None

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 16-AUG-2023

25. DATE OF ONSITE INVESTIGATION:

28. ACCIDENT CLASSIFICATION:

For Public Release 22-JUN-2023

26. Investigation Team Members/Panel Members: 29. ACCIDENT INVESTIGATION PANEL FORMED: NO

Alvin Obrien / Perry Brady /

27. OPERATOR REPORT ON FILE:

OCS REPORT:

30. DISTRICT SUPERVISOR:

Stephen Martinez

APPROVED

DATE: 08-AUG-2023

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 16-AUG-2023