

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT
GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

For Public Release

1. OCCURRED

DATE: 21-APR-2018 TIME: 0900 HOURS

2. OPERATOR: Anadarko Petroleum Corporation

REPRESENTATIVE:
TELEPHONE:

CONTRACTOR:
REPRESENTATIVE:
TELEPHONE:

- STRUCTURAL DAMAGE
- CRANE
- OTHER LIFTING
- DAMAGED/DISABLED SAFETY SYS.
- INCIDENT >\$25K
- H2S/15MIN./20PPM
- REQUIRED MUSTER
- SHUTDOWN FROM GAS RELEASE
- OTHER

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT: 8. OPERATION:

4. LEASE: G21444

AREA: KC LATITUDE:
BLOCK: 875 LONGITUDE:

5. PLATFORM: A (Lucius)
RIG NAME:

- PRODUCTION
- DRILLING
- WORKOVER
- COMPLETION
- HELICOPTER
- MOTOR VESSEL
- PIPELINE SEGMENT NO.
- OTHER

6. ACTIVITY: EXPLORATION(POE)
 DEVELOPMENT/PRODUCTION
(DOCD/POD)

9. CAUSE:

7. TYPE:

HISTORIC INJURY

- REQUIRED EVACUATION
- LTA (1-3 days)
- LTA (>3 days) 1
- RW/JT (1-3 days)
- RW/JT (>3 days)
- Other Injury

- EQUIPMENT FAILURE
- HUMAN ERROR
- EXTERNAL DAMAGE
- SLIP/TRIP/FALL
- WEATHER RELATED
- LEAK
- UPSET H2O TREATING
- OVERBOARD DRILLING FLUID
- OTHER _____

- FATALITY
- POLLUTION
- FIRE
- EXPLOSION

10. WATER DEPTH: 7000 FT.
11. DISTANCE FROM SHORE: 206 MI.

- LWC HISTORIC BLOWOUT
 UNDERGROUND
 SURFACE
 DEVERTER
 SURFACE EQUIPMENT FAILURE OR PROCEDURES

12. WIND DIRECTION:
SPEED: M.P.H.

13. CURRENT DIRECTION:
SPEED: M.P.H.

14. SEA STATE: FT.

15. PICTURES TAKEN:

16. STATEMENT TAKEN:

COLLISION HISTORIC >\$25K <=\$25K

17. INVESTIGATION FINDINGS:

For Public Release

On April 21, 2018 at approximately 0900 hours, at KC 875A (Lucius), a contract employee (CE) injured his right shoulder while attempting to carry two 20 lb scaffold boards.

As the CE was attempting to carry two 20 lb scaffold boards approximately 7 ft. long, he noticed a cable several feet high that crossed the walkway being used as an anchor for a welding enclosure. The CE repositioned to keep the boards from coming in contact with the cable and felt his shoulder pop. The medic examined the CE and found no concerns at that time. The medic contacted a physician and was instructed to give the CE Ibuprofen and an ice pack for the remainder of the day. The CE was cleared the following day to return to full duty.

On April 27, 2018 at approximately 0300 hours, the CE was lying in his bunk and felt what he thought was his shoulder popping out of place. The CE was transported to a medical facility for additional treatment. As per the Lessee's Incident Summary Report, the MRI determined the CE suffered a fracture in his labrum.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The CE should have requested help with carrying the two scaffold boards. This may have alleviated the CE's attempt to reposition while carrying the boards.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None

NA

ESTIMATED AMOUNT (TOTAL):

\$

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The BSEE Lafayette District office makes no recommendations to the Regional Office of Incident Investigations (OII).

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

None

25. DATE OF ONSITE INVESTIGATION:

28. ACCIDENT INVESTIGATION

26. INVESTIGATION TEAM MEMBERS:

PANEL FORMED: NO

Raymond Johnson / Wade Guillotte /

OCS REPORT:

30. DISTRICT SUPERVISOR:

Elliott S. Smith

APPROVED

DATE: **27-APR-2018**