UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF SAFETY AND ENVIRONMENTAL ENFORCEMENT GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

		For Public Release
1.	OCCURRED DATE: 04-FEB-2012 TIME: 0445 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Chevron U.S.A. Inc. REPRESENTATIVE: TELEPHONE: CONTRACTOR: Transocean Offshore REPRESENTATIVE: TELEPHONE:	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE X OTHER SBM spill
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G16942 AREA: WR LATITUDE: BLOCK: 29 LONGITUDE: PLATFORM:	PRODUCTION X DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
5.	RIG NAME: T.O. DISCOVERER INDIA	OTHER
6.	ACTIVITY: X EXPLORATION (POE) DEVELOPMENT/PRODUCTION	8. CAUSE:
7.	TYPE: HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days)	X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY POLLUTION FIRE EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	9. WATER DEPTH: 5193 FT.
		10. DISTANCE FROM SHORE: 139 MI.
		11. WIND DIRECTION: SE SPEED: 18 M.P.H.
		12. CURRENT DIRECTION: SE SPEED: 1 M.P.H.
		13. SEA STATE: 5 FT.
		14. PICTURES TAKEN: NO
		15. STATEMENT TAKEN: NO
MM	IS - FORM 2010	PAGE: 1 OF 5

EV2010R

On February 4, 2012, an employee was lining up to go overboard with seawater. A valve misaligned with the mud pits caused approximately 100 barrels of Synthetic Oil Based Mud (62 barrels oil) to be pumped into the Gulf of Mexico.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Employee failed to isolate one of the valves coming from one of the active pits. 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

-Inattention to detail; the employee did not ensure that the valve was fully closed before moving on to the next task.

20. LIST THE ADDITIONAL INFORMATION:

n/a

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

Loss of 100 barrels of SBM.

100 barrels of Synthetic Oil Based Mud spilled into the Gulf of Mexico.

ESTIMATED AMOUNT (TOTAL): \$21,195

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: YES

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

An E-100 was issued on Feb. 7, 2012 stating the following: On Feb. 4, 2012, at approximately 04:40, while preparing to pump seawater overboard from the Slug Tank, a valve coming from the Active Mud Pits was left in the open position allowing communication between the tank and pits. Failure to isolate the valve resulted in the release of 100 bbls. of SOBM into the Gulf of Mexico.

25. DATE OF ONSITE INVESTIGATION: 28. ACCIDENT CLASSIFICATION:

07-FEB-2012

MINOR

26. ONSITE TEAM MEMBERS: 29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Jeramie Liner / Cedric Bernard / Bryan Domangue James Richard /

APPROVED APPROVED DATE: 20-JUN-2012

27. OPERATOR REPORT ON FILE: NO

MMS - FORM 2010 EV2010R

PAGE: 3 OF 5 28-JUN-2012

POLLUTION ATTACHMENT

1.	VOLUME:	GAL	62	BBL	
		YARDS LONG X		YARDS	WIDE
	APPEARANC	E:			
2.	TYPE OF HYDROCARB	ON RELEASED:	OIL		
		[DIES	EL	
		[COND	ENSATE	
		[HYDR	AULIC	
		Γ	NATU	ral gas	5
		2	C OTHE	R Syn	thetic Oil Based Mud
3.	SOURCE OF HYDROCA	RBON RELEASED:	Human	error,	Synthetic Oil Based Mud.
4.	WERE SAMPLES TAKE	N? NO			
5.	WAS CLEANUP EQUIPMENT ACTIVATED? NO				
	IF SO, TYPE: SKIMMER CONTAINMENT BOOM ABSORPTION EQUIPMENT DISPERSANTS OTHER				
б.	ESTIMATED RECOVER	ү:	GAL		BBL
7.	RESPONSE TIME: HOURS				
8.	IS THE POLLUTION IN THE PROXIMITY OF AN ENVIRONMENTALLY SENSITIVE AREA (CLASS I)? NO				
9.	HAS REGION OIL SPILL TASK FORCE BEEN NOTIFIED? NO				
10.	CONTACTED SHORE: NO IF YES, WHERE:				
11.	WERE ANY LIVE ANIMALS OBSERVED NEAR: NO				
12.	WERE ANY OILED OR DEAD ANIMALS OBSERVED NEAR SPILL: NO				

MMS - FORM 2010 EV2010R