

U.S. Department of the Interior Minerals Management Service Gulf of Mexico OCS Region

Notice No. 068

November 9, 1977

OCS Operations Safety Alert

Explosion

An explosion recently occurred on an offshore production platform resulting in injuries to two men.

Two service company personnel were injured attempting to start an engine by using gas well pressure in lieu of compressed air. When they found that an air compressor was not available on the platform, they connected the engine air volume chamber into a 1750 psi gas well. When the well pressure was opened to the volume chamber to start the engine, the chamber exploded, scattered metal, and injured the two men.

To avoid a recurrence of this type of accident, the operator has informed all contract personnel that this method of starting engines will not be used. If this situation occurs again, operations will be shut down until the proper equipment is available to start the engine.

[signed] D.W. Solanas

Oil and Gas Supervisor

Field Operations

Gulf of Mexico Area

1 of 1 2/21/2012 2:04 PM