



NOTIFICATION OF INCIDENT(S) OF NONCOMPLIANCE
 You are hereby ordered to correct the identified Incident(s) of Noncompliance (INC(s) listed below. You have the right to appeal any INC Notification in accordance with Title 30 CFR part 290. You must file your appeal in the office of the official issuing this Notification. However, the filing of an appeal will not suspend the requirement to comply with this Notification.

Page of
 Date 03/25/2016
 Time (24-Hour Clock) 10:30
 BSEE Rep. (Print Last Name) Compo, Reeves, Naquin
 Complex/Rig ID No. 47916

BSEE Office Address BSEE HOUMA DISTRICT 3866 HIGHWAY 56 HOUMA, LA 70363	Lease No. G05809	Area and Block GC-18	Facility/Rig and Well No. Nobors MoDs 201	Complex/Rig ID No. 47916
	Lease Operator (Print) Whistler Energy II	Drill, Prod, P/L Contractor (Print) Nobors Offshore	Turnkey Company (Print) N/A	

Enforcement Action: W - Warning C - Component Shut-in S - Facility Shut-in

PINC No.	Enf. Action	Authority 30 CFR	INC Description and any Special Orders (shut-in of operations, facility, wells, etc.) Potential INC/PINC Guidelines at http://www.bsee.gov/Inspection-and-Enforcement/Inspection-Programs/Inspection-Programs/	Date Corrected
G-110	S	250.107(A)	<p>On March 10, 2016 A Nobors Offshore Corporation employee 4016 (contracted by Whistler Energy II) was fatality injured while attempting to chip and wash cement out of the rig's poor-boy degasser. Although not identified as a cause of the incident due to the ongoing BSEE investigation, the rig crew entered the poor-boy degasser without an approved confined space permit and oversight on the facility did not stop or prevent this activity from taking place.</p> <p>Note: The rig has been shut down since the incident and drilling operations shall not proceed until BSEE Houma District grants approval.</p> <p>A letter of explanation must be submitted to BSEE Houma District which describes the events that led up to the poor-boy degasser being filled with cement, starting with the well control event on (March 1, 2016) and ending with an explanation of the incident which resulted in the fatality on March 10, 2016</p>	

BSEE Representative Signature Clinton Compo	Operator Representative Print Last Name Gled Smith Signature [Signature] Date 3/25/2016
--	---

The recipient must report the date each INC was corrected no later than 14 DAYS from the date of issuance. If you cannot report this within the allotted time, you must obtain a waiver from the appropriate BSEE office. This process should ensure that company management is aware and acknowledges that INCs were issued on this facility, on this date, but in no way delays any enforcement action taken.

- The BSEE provides two options for reporting the resolution of the issues identified in the INC:
- Option 1 - When available, you may use the BSEE-provided web-based "INC Response" system to report INC resolution within the required time period and/or request a time extension waiver. Only persons registered with BSEE and authorized to represent your company may use this service. Information about registering and using the web-based system is available at www.bsee.gov.
 - Option 2- If the web-based system is not available, you must insert in the "Date Corrected" column the date each INC was corrected; sign and date a copy of this form; and return it to the BSEE office identified above no later than 14 DAYS from the date of issuance. If a copy cannot be returned within the allotted time, you must obtain an extension from the appropriate BSEE office.

Unless specifically ordered otherwise, the operator representative must certify that all component shut-in and facility shut-in INCs identified on