

**UNITED STATES DEPARTMENT OF THE INTERIOR
MARINE MINERALS ADMINISTRATION
GULF OF AMERICA OCS REGION**

NTL No. 2026-G03

Effective Date: 10/13/2026

**NOTICE TO LESSEES AND OPERATORS OF FEDERAL OIL AND GAS
LEASES AND PIPELINE RIGHT-OF-WAY HOLDERS
IN THE OUTER CONTINENTAL SHELF, GULF OF AMERICA OCS REGION**

Inspection and Reporting for Hurricane Isaias

The Marine Minerals Administration (MMA) Gulf of America OCS Region (GOAR) is issuing this Notice to Lessees and Operators and Pipeline Right-of-way Holders (NTL) pursuant to 30 CFR 250.106(b) and (c) to identify and describe the affected area for Hurricane Isaias and to elaborate on the inspections, plans, and reports needed due to known and potential damage to OCS facilities. This NTL also references NTL No. 2026-G02, effective August 10, 2026, entitled Post-Hurricane Inspection and Reporting which also provides guidance on the inspections you need to conduct and the reports you need to prepare, and NTL No. 2015-G02, effective July 27, 2015, entitled Hurricane and Tropical Storm Effects Reports for guidance on using either email or the eWell Permitting and Reporting System to report hurricane and tropical storm effects information.

Affected Area

For planning purposes, the initial affected area for Hurricane Isaias is the area that experienced hurricane force winds as defined by the National Hurricane Center. For Hurricane Isaias, the initial affected area is shown in red on the attached graphic (see the attached Figure No.1).

If necessary, the initial affected area for Hurricane Isaias may be updated by MMA with a revised NTL based upon additional information, such as updated hurricane metocean data, reports of platform damage outside the initial affected area, etc., which would redefine the affected area of Hurricane Isaias.

In addition, if you obtain data that indicates your facility should be included in the affected area as mentioned above, then it is MMA's expectation that you should also comply with NTL No. 2026-G02 and NTL No. 2015-G02.

If you have difficulty determining your location on the graphic, you may call either (504) 731-1493 or (504) 736-2876.

Fixed OCS Platforms and Structures, Floating OCS Structures, Moored Mobile Offshore Drilling Units and OCS Pipelines

See NTL No. 2026-G02 for details on the surveys and inspections you need to conduct for Fixed OCS Platforms and Structures, Floating OCS Structures, Moored Mobile Offshore Drilling Units, and OCS Pipelines. For Fixed OCS Platforms and Structures:

1. Begin immediately to conduct the required Level I and Level II/III surveys. We encourage you to inspect first the older platforms located nearest the eye center storm tracks, and then gradually inspect those platforms toward the outer limits of the affected area. Make sure that you complete all surveys by April 7, 2027 (180 days from impact date).
2. In addition, if your Level I, II or Level III surveys find structural damage, complete a structural analysis and perform any necessary repairs. Please be reminded that 30 CFR 250.900(b)(3) and 30 CFR 250.905 require you to obtain approval from the MMA GOAR before you make major repairs of any damage. Complete all work to correct any damage you find during a platform survey before June 1, 2027.
3. By December 9, 2026 (60 days from impact date), submit the information listed below by e-mail to structures@bsee.gov:
 - A list of all your OCS platforms and other structures that are required to be surveyed.
 - For each listed structure, an initial inspection plan that generally describes the work you will perform to determine the condition of the structure; and
 - A timetable that shows how you will complete all inspections by April 7, 2027 (180 days from impact date).

For Pipelines:

Pursuant to 30 CFR 250.1005(a), you must conduct inspections of pipeline routes at intervals and using methods prescribed by MMA. Under this authority, the MMA GOAR hereby directs you to conduct the required inspections by April 7, 2027 (180 days from impact date) for pipelines in the affected area.

Complete all work to correct any damage you find during a pipeline inspection before June 1, 2027. Be reminded that before you conduct any repairs, you are to submit a repair procedure for review and acceptance to the MMA GOAR Pipeline Section.

Safety Device Testing Departures and Returning to Production

See NTL No. 2026-G02 for guidelines pertaining to time extensions with respect to safety device testing, casing pressure monitoring, and pollution.

If you are unable to perform your required safety device tests, casing pressure monitoring, or pollution inspections by November 24, 2026 (45 days from impact date), contact the appropriate MMA GOAR District Office for a further possible extension.

Coast Guard Annual Safety Inspections

Departures for performing United States Coast Guard (USCG) Annual Safety Inspections may be granted by the appropriate USCG district office.

Hurricane and Tropical Storm Effects Reports

See NTL No. 2026-G02 for guidance on using either email or the eWell Permitting and Reporting System to report hurricane and tropical storm effects information.

Guidance Document Statement

The MMA issues NTL's as guidance documents in accordance with 30 CFR 250.103 to clarify, supplement, and provide more detail about certain MMA regulatory requirements and to outline the information you provide in your various submittals. Under that authority, this NTL sets forth a policy on and an interpretation of a regulatory requirement that provides a clear and consistent approach to complying with that requirement. However, if you wish to use an alternate approach for compliance, you may do so, after you receive approval from the appropriate MMA office under 30 CFR 250.141.

Paperwork Reduction Act of 1995 Statement

The Paperwork Reduction Act of 1995 (PRA) (44 U.S.C. 3504 et seq.) requires us to inform you that the MMA collects this information to carry out its responsibilities under the OCS Lands Act, as amended. The MMA will use the information to determine if the structural integrity of platforms and pipelines may have been adversely affected by Hurricane Isaias, if any damage poses a threat to continued safe operations or the environment, and, if so, whether to require correction action on damaged structures. Responses are mandatory. No proprietary data are collected. The Office of Management and Budget (OMB) has approved the collection of information pertaining to OCS Pipelines and Pipeline Rights-of-way at 30 CFR 250, Subpart J, and assigned OMB Control Number 1014-0016; and for Platforms and Structures at 30 CFR 250, Subpart I, and assigned OMB Control Number 1014-0011. The MMA estimate the public reporting burden to average approximately 144 hours per respondent. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid Office of Management and Budget (OMB) control number.

Contacts

Please address any questions regarding platform surveys or reports to the Chief of the MMA GOAR Office of Structural and Technical Support by telephone at (504) 736-2895 or by e-mail at structures@bsee.gov. Address any questions regarding moored rig inspections or issues to the MMA GOAR Well Operations Support Section by telephone at (504) 736-7646 or by email at omm_dfo_woss@bsee.gov. Address any questions regarding pipeline inspections or reports to the Chief of the MMA GOAR Pipeline Section by telephone at (504) 736-2895 or by e-mail at pipelines@bsee.gov. Address any questions regarding safety device inspection and testing to the appropriate MMA GOAR District Office.

BRYAN

DOMANGUE

Digitally signed by
BRYAN DOMANGUE
Date: 2026.10.13
15:30:34 -05'00'

Bryan Domangue, Regional Director
Gulf of America OCS Region
Marine Minerals Administration

Figure 1: Hurricane Isaias Affected Area

[Area of Hurricane Force Winds is in Red - Plotted using information from NOAA – National Hurricane Center]

