Civil Penalties Program

The goal of the BSEE OCS Civil Penalties Program is to assure safe and clean operations on the OCS. Through the pursuit, assessment, and collection of civil penalties and referrals for the consideration of criminal penalties, the program is designed to encourage compliance with OCS statutes and regulations.

Civil Penalties Summary (as of 2/15/2025)

Penalties Paid for FY2022 (10/1/2021-9/30/2022)

Operator Name and	Violation and Date(s)	Penalty Paid &	Regulation(s)
Case #		Date Paid	Violated 30 CFR
W&T Offshore, INC	Flash fire resulting in injury.	\$46,000.00	G-110
G-2018-020	Fuel gas was piped into the platform air supply after an air compressor was taken out of service.	January 11, 2022	30 CFR 250.107
	April 11, 2018		
Eni US Operating Co.	Improper compressor installation	\$28,400.00	G-110
Inc	resulted in an explosion.		
G-2020-007	December 23, 2018	February 22, 2022	30 CFR 250.107
Castex Offshore, INC	Failure to properly maintain the	\$45,463.00	P-130
000000000000000000000000000000000000000	firewater pump engine.	+ 10, 100,000	1 100
G-2020-035	May 3, 2020	June 15, 2022	30 CFR 250.859(a)
Castex Offshore, INC	Unsecured floor grating on the	\$56,000.00	G-110
	well deck and failing to notify BSEE Inspectors of this known hazard before the Inspectors	June 15, 2022	30 CFR 250.107
	walked through the facility.		G-111
G-2020-50	June 1, 2020		30 CFR 250.107
DCOR, LLC.	During repairs to the galley floor	\$48,862.00	G-112
P-2021-002	on Platform Gilda, operated by DCOR, LLC, a man-overboard incident occurred resulting in one fatality and a serious injury.	August 4, 2022	30 CFR 250.107
	December 2, 2022		
Talos Petroleum LLC.	Failure to operate in a safe and	186,000.00	G-110
C 2021 002	workmanlike manner; Failure to ensure personnel had usable	April 7 2022	30 CFR 250.107
G-2021-002	firefighting equipment, failure to follow approved EBP, and failure	April 7, 2022	G-313
	to prevent materials from falling into the OCS waters, which		30 CFR 250.113(c)(2)(ii
	resulted in fatality and		
	associated unsafe hot work operations.		G-302
			30 CFR 250.111
	February 17, 2018 (G-110 and G313)		E-108
	February 16, 2018 - February 17, 2018 (G-302 and E-108)		30 CFR 250.300(b)(6)
Talos Petroleum LLC.	Failure to follow approved scope of work	\$46,000.00	G-110
C_2021_012	which resulted in an unconctrolled drope of the crane crane boom.	Tanuaru 11 0000	30 CER 250 107
G-2021-012	October 15, 2019	January 11, 2022	30 CFR 250.107

McMoRan Oil and Gas LLC.	A G-111 INC was issued to McMoRan Oil & Gas LLC on December 9, 2020, for	\$92,000.00	G-111
G-2021-016	multiple violations including failing to address numerous areas of corroded grating and failing to maintain handrails in a safe condition at their	April 7, 2022	30 CFR 250.107
	HI A531 A platform.		
	December 9, 2020		
Talos Oil and Gas LLC	An incident occurred that resulted in a crewmember losing his thumb	\$46,000	G-110
G-2021-023	and 2 fingers.	June 6, 2022	30 CFR 250.107
	August 13, 2020		
Cox Operating LLC.	Identified areas of severe metal loss, scaling, and perforations in	\$57,400.00	G-110
G-2021-025	structural members throughout facility including damage caused	February 17, 2022	30 CFR 250.107
	by storms.	2022	G-111
	June 4, 2020		30 CFR 250.107
COX Operating LLC.	Failure to operate in a safe and workmanlike manner during	\$67,500.00	E-108
G-2021-026	construction operations and failed to prevent the disposal	February 3, 2022	30 CFR 250.300(b)(6)
	of debris (partial staircase) which fell into the water		G-110
	during cutting operation.		30 CFR 250.107
COX Operating LLC.	January 24, 2020 Failure to Correct Unsafe conditions	\$13,250.00	G-111
G-2021-030	on the facility due to corrosion and/ or neglect that posed an immediate	March 14, 2022	30 CFR 250.107
0 2021 000	threat of harm to personnel, the facility, and the environment.	Haren 14, 2022	50 611 230.107
malas palasla a IIG	January 1, 2021 - March 16, 2021	<u> </u>	D 500
Talos Petroleum LLC.	Large gaps in the sealing surfaces, missing gaskets, and/or	\$46,000.00	P-526
G-2021-031	missing hardware on the burners of the NBK-1700 Electrostatic Treater	January 11, 2022	30 CFR 250.850
	were found (rendering flame arresters inoperable).		
	September 2, 2020		
Tana Exploration Company LLC.	Multiple violations, including Failure to operate in a safe and workmanlike manner by failure to use	\$122,155.00	G-110
G-2021-032	proper safe lifting practices; Failure to designate a fire watch	August 22, 2022	30 CFR 250.107
	during welding operations; Failure remove any equipment containing hydrocarbons or other flammable		G-311
	substances prior to welding operations		30 CFR 250.113(c)(2)
			G-303
	September 6, 2020		30 CFR 250.113(a)
Cox Operating LLC.	Failure to correct extensive corrosion to structural supports,	\$22,250.00	G-111
G-2021-033	grating, and fasteners throughout facility.	September 21, 2022	30 CFR 250.107
Cox Operating LLC.	December 9, 2020 - January 6, 2021 Unsafe conditions on the	\$23,000.00	G-111
	facility that posed an immediate		
G-2021-035	threat to personnel, the facility, and/or the environment.	July 5, 2022	30 CFR 250.107

	November 4, 2020 - November 5, 2020		
Cox Operating LLC.	Utilization of a non-intrinsically	\$29,431.00	G-110
	safe fan and extension cord in a	,	
G-2021-038	Class I Division II area.	July 22, 2021	30 CFR 250.107
	July 22, 2021		
Cox Operating LLC.	Failure to Correct violation for	\$10,250.00	G-111
	the Failure maintain multiple area		
G-2021-040	in a safe and workmanlike manner, due to corrosion.	September 22, 2022	30 CFR 250.107
	December 21, 2020 - February 16, 2021		
Cox Operating LLC.	Extensive corrosion of structural members.	\$48,862.00	G-111
G-2021-041	members.	September 2,	30 CFR 250.107
	January 6, 2021	2022	
Arena Offshore, LP	A P-130 INC was issued to Arena	\$48,862.00	P-130
G-2021-042	Offshore, LP on August 18, 2021, for failing to maintain or ensure the	NG 0000	
G-2021-042	good working order of the FWP at EC 328 B.	May 6, 2022	30 CFR 250.859(a)
	August 18, 2021		
GoMex Energy Offshore,	A P-130 INC issued for failure to maintain	\$30,486.00	P-130
Ltd.	the AFFF system and was discovered to not		
G-2022-002	be in good working order.	June 16, 2022	30 CFR 250.859(a)
G 2022 002	July 22, 2021 - July 23, 2021		
Energy XXI GOM, LLC	Failure to Correct a violation for the Failure to maintain the facility in a safe condition and repair multiple areas of	\$8,750.00	G-111
	corrosion.	September 30,	30 CFR 250.107
G-2022-005	March 26, 2021 - May 16, 2021	2022	
Murphy Exploration & Production Company -	Failure to perform operations in a safe and workmanlike manner during multiple phases	\$30,486.00	G-110
USA	of the floating oil removal operations resulting in a dropped object/material	August 31, 2022	30 CFR 250.107
G-2022-007	overboard incident February 2, 2022		
Anadarko Petroleum	Failing to ensure safe crane use	\$48,862.00	G-110
Corporation	on the Diamond Ocean		20.077.050.107
G-2022-009	Blackhawk drillship, resulting in the uncontrolled sliding of the	September 13, 2022	30 CFR 250.107
0 2022 007	High-Pressure Wellhead (HPW)	2022	
	housing near multiple personnel.		
	March 10, 2021		
	۱	I	.

24 cases were closed during FY2022 with payments totaling \$1,202,269.00