

Safety Alert No. 501 June 9, 2025

Contact: <u>bseepublicaffairs@bsee.gov</u>

Phone: (800) 200-4853

BSEE Identifies Bypassed Safety Device Deficiencies during Risk-Based Inspections



Figure 1: An example image of electronic monitoring system.

Members of the Bureau of Safety and Environmental Enforcement (BSEE) Gulf of America Region (GOAR) identified a potential risk associated with bypassed safety devices and inconsistent interpretation of regulations after multiple incidents of noncompliance were issued associated with the operator's failure to comply with 30 CFR 250.869 and 30 CFR 250.870 in 2025.

The BSEE Performance-Based Risk Inspection (PBRI) covered five assets (all production platforms) in the GOAR, which five separate operators operated.

What BSEE's PBRI Found:

- Multiple facilities and operators had internal policies to flag/tag temporarily out-ofservice safety devices and track bypasses; however, inspections revealed that facility personnel were not adequately documenting these bypasses electronically or in hard copy.
- BSEE inspection teams observed several facilities' data historians to be nonoperational. A data historian is a software application that collects, stores, and retrieves time-series data from various sources, allowing operators to analyze

historical data related to alarms, control actions, and other operational events.

- BSEE found that operators commonly utilized a "maintenance bypass" whenever
 they needed a bypass. A "maintenance bypass" offers more robustness than a
 standard bypass. With a standard bypass, an operator can choose a specific
 function to bypass for a particular device. In contrast, a "maintenance bypass"
 stops the device from triggering the safety system across the entire 4-20 mA
 range and beyond, even if the device experiences a fault or loses power.
- "Maintenance bypasses" are popular because operators can use the same bypass function for startup, maintenance, and testing, thereby preventing nuisance trips. However, during startup, a "maintenance bypass" may be selected for a pressure transmitter that provides both pressure safety high (PSH) and pressure safety low (PSL) functions. In this case, the PSH and PSL are disabled, rather than just bypassing the PSL. BSEE has found that in some startup situations, it is unnecessary to bypass the PSH. In these cases, this practice fails to meet the "minimum" number of devices that can be bypassed according to 30 CFR 250.869, which increases operational risk by disabling primary pressure protection.
- BSEE found that some platforms had actions entitled "group bypass selectors."
 This option bypasses several devices at once and is useful for some applicable operations. In most scenarios, control room operators and their competency were the only barrier to ensuring the minimum number of devices in bypass. For example, the operator did not have a preset list of minimum bypasses that are needed for common operations on the facility.
- BSEE found that some operators kept devices in bypass for longer durations.
 Operators cited nuisance trips and alarms, such as sea state and weather, for
 reasons associated with bypasses for extended periods on sumps and
 emergency shutdown devices (ESDs) at the boat landing. One operator had
 examples of allowable bypasses extending for 12 hours and only requiring a
 conversation with a control room operator and the offshore installation manager.
- During the inspection, multiple operators indicated that they were allowed to
 place devices in bypass for "repair" and "troubleshooting." Multiple operators had
 different interpretations of 30 CFR 250.869A, which states, "Surface or
 subsurface safety devices must not be bypassed or blocked out of service unless
 they are temporarily out of service for startup, maintenance, or testing."
 Specifically, "maintenance" was not well defined within operator procedures.
- Multiple operators had safety system bypass procedures requiring certain
 personnel to review adherence to the operator's procedure by conducting an
 audit. The audit's results and actions were also required to be documented and
 shared with relevant personnel. Unfortunately, the operator did not provide audits

- of this nature or scope were not provided by the operator for the subject facilities to BSEE during the PBRI.
- BSEE found one instance where an operator had mistakenly bypassed the entire safety system while the facility was producing. In this case, a project team altered ladder logic to bypass groups of devices that were needed for the construction process while the facility was offline. However, when the facility went back online, these ladder logic changes were not reverted, and entire groups of devices were unknowingly in bypass.

As a result of these findings, BSEE recommends:

- Operators should document all authorized safety system bypasses, inhibits, or overrides in logs that capture identification tags, equipment identification, reasons, applications, and removal details. If data historians cannot capture this data, a written process should document all bypasses.
- Operators should document any changes to the ladder logic needed for construction and ensure that these changes are reverted before the project's completion.
- Operators should evaluate their offshore data historian and determine if they can record and store electronic data records when operator interventions occur.
- Industry should ensure that a computer-based system's human-machine interface (HMI) can display all bypassed safety devices and operational conditions.
- Industry should review and document bypasses associated with "repair" and "troubleshooting." Any bypass should include the date and time of the installation and removal of the bypass and the reason. Also, if the bypass is associated with any "repairs" or "troubleshooting," supporting documentation should be included within the bypass log to capture the associated work activity. Operators should consider referencing API RP 14C 8th edition for bypass applications regarding "maintenance" activities: Maintenance bypasses allow repairing a failed or failing safety function device without a process upset.
- Operators should develop systems to verify compliance with their safety system bypass procedures.

- BSEE -

A **Safety Alert** is a tool used by BSEE to inform the offshore oil and gas industry of the circumstances surrounding a potential safety issue. It also contains recommendations that could assist avoiding potential incidents on the Outer Continental Shelf.