Civil Penalties Program

The goal of the BSEE OCS Civil Penalties Program is to assure safe and clean operations on the OCS. Through the pursuit, assessment, and collection of civil penalties and referrals for the consideration of criminal penalties, the program is designed to encourage compliance with OCS statutes and regulations.

Civil Penalties Summary: Penalties Paid for FY2019

(10/1/2018-9/30/2019)

(10/1/2018-9/30/2019) Operator Name and Case #	Violation and Date(s)	Penalty Paid &	Regulation(s) Violated 30
		Date Paid	CFR
Fieldwood SD Offshore	Crane boom collapsed	\$ 43,576.00	G110
TIC	December 1, 2015	December 19,	30 CFR 250.107(a)
G-2016-015	2000,001 1, 2010	2018	30 CIR 230:107(a)
		4 00 100 00	2010
BHP Billiton Petroleum (GOM) Inc.	an incident occurred on the Transocean Deepwater Invictus	\$ 38,100.00	G110
(3011) 1110.	Drillship located at Lease OCS	November 11,	30 CFR 250.107(a)
G-2016-024	G-20084, Green Canyon	2018	
	654 (GC 654), Well No. I001 operated by BHP. The incident		
	involved the rig.		
	Involved one rig.		
	March 30, 2016		
Fieldwood Energy Offshore LLC	Shutdown valves (SDV) bypassed on two incoming pipelines.	\$ 120,000.00	Two P103's
Offshore LLC	on two incoming pipelines.	December 19,	30 CFR 250.803(c)
G-2016-028	Mar. 20 2015	2018	00 0111 2001000 (0,
Talos Oil and Gas LLC	May 20, 2015 Falling material in a confined	\$ 87,152.00	G110
	workspace (Mud/Gas Separator)	,	
G-2017-015	resulting in a fatality.	August 23,	30 CFR 250.107(a)
	March 9, 2016	2019	
Energy XXI GOM, LLC	Failure to maintain accessable	\$ 31,750.00	G111
,	evacuation routes and failure	,	
G-2017-030	to provide sufficient barriers	November 1,	30 CFR 250.107
	to out-of-service locations.	2018	
	March 28, 2017		
Fieldwood SD Offshore	Hot work being conducted within	\$ 36,750.00	G303
LLC	35ft of flammable substances.	December 19,	30 CFR 250.113(a)
G-2017-038	June 2, 2017	2018	30 CFR 230.113(a)
Fieldwood SD Offshore	An incident resulting in a	\$ 43,576.00	G110
LLC	flash fire injured one person		
	causing him to fall overboard	October 22,	30 CFR 250.107
G-2018-007	into the water on Lease OCS.	2018	
	August 10, 2017		
GoMex Energy Offshore,	During the course of an inspection, BSEE observed an	\$ 21,750.00	G303
Lta.	atmospheric tote tank	October 18,	30 CFR 250.113(a)
G-2018-008	containing a flammable	2018	, ,
	substance located within 35		
	feet of welding operations, and not rendered inert or protected		
	with flame-proofed covers.		
	-		
Arona Offahara ID	February 9, 2018	\$ 16,300.00	C110
Arena Offshore, LP	During the course of an inspection, workers initiated	₽ 10,3UU.UU	G110
G-2018-010	an incident that caused a	October 16,	30 CFR 250.107
	release of 1000 psi gas. The	2018	

	workers did not properly plan the job to eliminate hazards.		
	February 1, 2018		
Cox Operating, L.L.C.	According to the investigation	\$ 70,749.00	G303
G-2018-012	findings and documents submitted to BSEE, a small fire	January 25,	30 CFR 250.113(a)
	occurred while the workers were performing hot work for the	2019	
	installment of temporary		
	quarters and associated equipment for workover		
	operations.		
	February 5, 2018		
ANKOR Energy LLC	Crane lifting operations resulted in an employee hand	\$ 38,100.00	G110
G-2018-014	injury.	November 9,	30 CFR 250.107
	April 12, 2018	2018	
Shell Offshore Inc.	During the course of an inspection, BSEE discovered an	\$ 26,750.00	G110
G-2018-015	open hole that was not properly	October 22,	30 CFR 250.107
	barricaded to protect personnel from entering the hazardous	2018	
	area.		
	April 20, 2018		
Fieldwood Energy LLC	During a BSEE inspection, the hydraulic control line for the	\$ 26,750.00	P103
G-2018-022	B-19 well SCSSV was found tie- wrapped in the closed position,	April 2, 2019	30 CFR 250.869(a)
	rendering the safety device	2019	
	bypassed, without being flagged or actively monitored.		
Anadarko Petroleum	July 26, 2018 According to the investigation	\$ 38,100.00	G110
Corporation	findings, workers were in the process of removing the rigs	March 7,	30 CFR 250.107
G-2018-023	Blowout Preventers (BOPs), and	2019	
	High-Pressure Riser System, when the Lateral Support Guide		
	frame they were utilizing as a work platform, fell		
	approximately 17 feet,		
	injuring two of the workers.		
Fieldwood Energy LLC	May 19, 2018 A G-110 INC was issued at WD	\$ 26,750.00	G110
	110 to Fieldwood Energy, LLC on		
G-2018-025	July 12, 2018 due to the improper operating, and	April 12, 2019	30 CFR 250.107
	subsequent exploding, the wells SSV actuator on January 18,		
	2018.		
	January 18, 2018		
Shell Offshore Inc.	Noble Drilling Services, Inc. (Noble) Derrickman who was	\$ 43,576.00	G110
G-2018-026	assisting as Floorman for the	March 15,	30 CFR 250.107
	subject lifting operations sustained injury when a chiksan	2019	
	assembly. Fell on his foot during lift.		
	June 25, 2018		

Shell Offshore Inc.	An INC was issued at GC 158 on	\$ 39,000.00	E100
	May 13, 2016, due to Shell		
G-2018-027	Offshore Inc. failing to	August 28,	30 CFR 250.107(a)
	prevent the discharge of	2019	
	hydrocarbons into the Gulf of		
	Mexico. The incident occurred		
	at the Shell Glider field (GC		
	248).		
	May 12, 2016		
Shell Offshore Inc.	Incident - Explosion and a	\$ 89,350.00	L126
	subsequent fire on the platform		
G-2019-007	(Enchilada) during pig loading	August 15,	30 CFR 250.1000(a)
	operations caused injuries to	2019	
	personnel and >\$25,000 in		G110
	damage to the facility.		30 CFR 250.107
	November 8, 2017		30 CFR 230:107
Walter Oil & Gas	A pollution event (>50 bbl)	\$ 75,800.00	G110
Corporation	occurred during mud transfer	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
_	operations.	June 3, 2019	30 CFR 250.107
G-2019-010			
	September 3, 2018		E100
			20 077 050 2007
			30 CFR 250.300(a)

19 cases were closed during FY2019 with payments totaling \$913,879.00