Civil Penalties Program

The goal of the BSEE OCS Civil Penalties Program is to assure safe and clean operations on the OCS. Through the pursuit, assessment, and collection of civil penalties and referrals for the consideration of criminal penalties, the program is designed to encourage compliance with OCS statutes and regulations.

Civil Penalties Summary:

Penalties Paid for FY2022 (10/1/2021-9/30/2022)

Operator Name and	Violation and Date(s)	Penalty Paid &	Regulation(s)
Case #		Date Paid	Violated 30 CFR
W&T Offshore, INC	Flash fire resulting in injury. Fuel gas was piped into the	\$46,000.00	G-110
G-2018-020	platform air supply after an air compressor was taken out of service.	January 11, 2022	30 CFR 250.107
	April 11, 2018		
Eni US Operating Co.	Improper compressor installation	\$28,400.00	G-110
Inc	resulted in an explosion.	February 22, 2022	30 CFR 250.107
G-2020-007	December 23, 2018	_	
DCOR, LLC.	During repairs to the galley floor	\$48,862.00	G-112
DOOR, LLC.	on Platform Gilda, operated by	740,002.00	G-112
P-2021-002	DCOR, LLC, a man-overboard incident occurred resulting in one fatality and a serious injury.	August 4, 2022	30 CFR 250.107
	5 1 0 0000		
Talos Petroleum LLC.	December 2, 2022 Falling crane boom.	\$46,000.00	G-110
Tatos rectoream and.	railing clane boom.	\$40 , 000.00	0 110
G-2021-012	October 15, 2019	January 11, 2022	30 CFR 250.107
McMoRan Oil and Gas	A G-111 INC was issued to McMoRan	\$92,000.00	G-111
LLC. G-2021-016	Oil & Gas LLC on December 9, 2020, for failing to address numerous areas of corroded grating and	April 7, 2022	30 CFR 250.107
G-2021-010	failing to maintain handrails in a safe condition at their HI A531 A platform.		
	May 18, 2020, to December 9, 2020		
COX Operating LLC.	Debris (partial staircase) fell into the water during cutting	\$67,500.00	E-108
G-2021-026	operation.	February 3, 2022	30 CFR 250.300(b)(6)
	January 24, 2020, to January 25, 2020		G-110
	2020		30 CFR 250.107
Talos Petroleum LLC.	Large gaps in the sealing	\$46,000.00	P-526
G-2021-031	surfaces, missing gaskets, and/or missing hardware on the burners of	January 11, 2022	30 CFR 250.850
	the NBK-1700 Electrostatic Treater were found (rendering flame arresters inoperable).	- ,	
	September 2, 2020		
Tana Exploration	September 2, 2020	\$122,155.00	G-110
Company LLC.		August 22, 2022	30 CFR 250.107
G-2021-032		1149406 22, 2022	
	September 6, 2020		G-311

	T	T	
			30 CFR 250.113(c)(2)
			G-303
			30 CFR 250.113(a)
Cox Operating LLC.	Extensive corrosion of structural members.	\$48,862.00	G-111
G-2021-041	January 6, 2021	September 2, 2022	30 CFR 250.107
Arena Offshore, LP	A P-130 INC was issued to Arena Offshore, LP on August 18, 2021,	\$48,862.00	P-130
G-2021-042	for failing to maintain or ensure the good working order of the FWP at EC 328 B.	May 6, 2022	30 CFR 250.859(a)
	August 18, 2021		
Murphy Exploration & Production Company -		\$30,486.00	G-110
USA G-2022-007	February 2, 2022	August 31, 2022	30 CFR 250.107
G-2022-007			
Anadarko Petroleum Corporation	Failing to ensure safe crane use on the Diamond Ocean	\$48,862.00	G-110
G-2022-009	Blackhawk drillship, resulting in the uncontrolled sliding of the High-Pressure Wellhead (HPW) housing near multiple personnel.	September 13, 2022	30 CFR 250.107
	March 10, 2021		

12 cases were closed during FY2022 with payments totaling \$673,989.00