SEQ_NUM	Date_Occurre	d Lease_Number	Area_Block	Accident_Type	Panel_Distric	Status
86 21		012 G04131 013 G00572	GC 19 EI 193	- RW/JT (>3 days) - Required Evacuation - Hand Injury - Required Evacuation	DISTRICT DISTRICT	Complete Complete
33	1/26/2	013 G06975	MC 709	- Fire	DISTRICT	Pending
35	1/17/2	013 G26519	HI A119	- Spill	DISTRICT	Pending
68	9/28/2	012 G02027	WC 639	- RW/JT (>3 days) - Required Evacuation - Hand Injury	DISTRICT	Complete
	9/5/2					
75	5	G02832	WC 205	- LTA (>3 days) - Required Evacuation - Other Lifting Device - Injury to Fingers	DISTRICT	Complete
89		005517	EI 325	- LTA (>3 days) - Required Evacuation - Fire - Flash Burn	DISTRICT	Complete
94	7/21/2	012 G02091	VR 340	- Incident >\$25K - Crane	DISTRICT	Complete
95 111 117 150	5/15/2 3/5/2	012 G02857 012 G15781 012 G14364 011 G22188	EC 42 HI A7 EC 129 MI A5	<ul> <li>Incident &gt;\$25K - Structural Damage</li> <li>Pollution - Incident &gt;\$25K - Crane - Structural Damage - Well Control Incident</li> <li>LTA (&gt;3 days) - Required Evacuation - Falling Object</li> <li>Crane</li> </ul>	DISTRICT DISTRICT DISTRICT DISTRICT	Complete Complete Complete
158	4/18/2	011 G02241	WC 643	- Fatality - Crane	PANEL	Complete
177	9/29/2	<sup>010</sup> G17232	EB 164	- Pollution - TA'd Well Leak	DISTRICT	Complete
187	5/28/2	<sup>010</sup> G02560	WC 630	- LTA (>3 days) - Required Evacuation - Fire - Cutting torch fire	DISTRICT	Complete

192	4/17/2010 <sub>00442</sub>	EI 128A	- Fire	DISTRICT	Complete
239	8/26/2009 G03135	VR 267	- Pollution	DISTRICT	Complete
247	7/12/2009 G05625	ST 245	- Incident >\$25K - Crane - Structural Damage	DISTRICT	Complete
264	5/1/2009 <sub>G04935</sub>	MC 20	- Fire - Drawworks Failure	DISTRICT	Complete
315	7/13/2008 <sub>G10815</sub>	ST 68	- Fire	DISTRICT	Complete
321	6/10/2008 G23857	EI 56	- LTA (1-3) days - Required Evacuation	DISTRICT	Complete
346	4/13/2008 <sub>G04427</sub>	VR 318	- Fatality	DISTRICT	Complete
375	1/6/2008 G03323	EC 220	- Other Injury - Crane	DISTRICT	Complete
464	2/11/2007 G14159	HI 154	- Fire	DISTRICT	Complete
465	2/10/2007 G14159	HI 154	- Fire	DISTRICT	Complete
556	2/20/2006 G03242	HI A466	- Blowout - Fatality - Pollution	PANEL	Complete
723	7/5/2003 G18165	EW 827	- Fatality - Subsea Explosion-diving event	DISTRICT	Complete
1222	12/7/1996 G04228	SS 133	- Fire - Injury - Fatality	DISTRICT	Complete
154	5/22/2011 00054	EI 129	- LTA (>3 days) - Required Evacuation - Crane - Eight fall 70 feet into Gulf	DISTRICT	Complete

938 209 1154	G04826 12/30/2009 G16645 6/19/1997 G08443	SS 332 MC 737 ST 75	<ul><li>- Pollution</li><li>- Pollution - Incident &gt;\$25K - Leaking P&amp;A'd Subsea Wellhead</li><li>- Pollution</li></ul>	DISTRICT DISTRICT DISTRICT	Complete Complete Complete
	3/9/1996				
1285	G09762	EW 482	- Pollution	DISTRICT	Complete
730	5/29/2003 G24929	SS 145	- Fire - Pollution	DISTRICT	Complete
	5/31/2013				
2	G22606	VR 52	- Fire - Incident >\$25K	DISTRICT	Complete
244	7/25/2009 G23900	SS 142	- Pollution - Incident >\$25K - Hurricanes Katrina and Rita	DISTRICT	Complete
	11/30/2008				
292	G01072	WD 40	- Fire - Incident >\$25K	DISTRICT	Complete
349	4/5/2008 00425	EI 63	- LTA (>3 days) - Required Evacuation - High Press. Gas Meter Release	DISTRICT	Complete
359	3/1/2008 G17958	EI 43	- Structural Damage	DISTRICT	Complete

	11/15/2007				
389	G02185	SP 78	- LTA (>3 days) - Required Evacuation	DISTRICT	Complete
417	8/23/2007 G02181	SP 57	- RW/JT (>3 days) - Required Evacuation	DISTRICT	Complete
	2/17/2007				
462	G16702	GC 177	- Pollution	DISTRICT	Complete
	2/4/2007				
470	G13035	MP 261	- LTA (>3 days) - Required Evacuation	DISTRICT	Complete
587	8/20/2005 G05537	SS 80	- Fire	DISTRICT	Complete
602	6/24/2005 G03601	WD 62	- Explosion - Injury	DISTRICT	Complete
659	7/18/2004 G01777	GA 255	- Fire - Pollution	DISTRICT	Complete
700	11/28/2003 G04475	WD 143	- Pollution	DISTRICT	Complete
702	11/21/2003 G01193	SM 57	- Fire	DISTRICT	Complete
	1/16/2003				
759	G03340	BS 53	- Explosion - Fire - Injury - Fatality - helicopter crash	DISTRICT	Complete

839	10/10/2001 G04877	SS 322	- Fire	DISTRICT	Complete
892	8/16/2000 G04834	MP 265	- Fire	DISTRICT	Complete
	8/15/2000				
895	00015	ST 53	- Fire	DISTRICT	Complete
	4/5/2000				
921	G04586	HI A472	- Pollution	DISTRICT	Complete
964	9/7/1999 G01607	SP 55	- Pollution	DISTRICT	Complete
1008	10/22/1998 G04826	SS 332	- Fire	DISTRICT	Complete
	3/28/1998				
1068	G03157	EI 365	- Fire - Construction	DISTRICT	Complete
1136	8/21/1997 G06643	EC 300	- WELLHEAD SEAL LEAK	DISTRICT	Complete

LEASE EFF DT	DateOccurred	LEASE EXPIR DT	OSM Notes		
	<b>Date Occarred</b>		Event is associated with a ROW platform located on GC 19 and		ļ
19791001	20120810	20081228	previously under the authority of lease G04131.	ROW	
19550901	20130330	20111031	Incident occurred on a structure being decommissioned.	DECOM	
			Incident occurred while plugging a well on the terminated		
19840701	20130126	19891001	lease.	DECOM	
			Occurred during permanent abandonment operations of a		
20041101	20130117	20091030	well on a relinquished lease.	DECOM	
			Occurred during decommisioning operations on a terminated		
19710201	20120928	20090812	lease.	DECOM	
			Latest lease number is G27006, but this incident occurred		
			during P&A operations on wells associated on G02832 and a		
19741201	20120905	20040510	structure that had been assigned to RUE G23635.	DECOM	
			Event occurred during P&A of a well on terminated lease		
19830701	20120803	20091031	G05517.	DECOM	
			Event occurred during P&A of a well on terminated lease		
19710101	20120721	20111027	G02091.	DECOM	
			Occurred during well abandonment operations on a		
19741201	20120720	20120115	terminated lease.	DECOM	
19951101	20120515	20080404	Occurred during P&A activities on a terminated lease.	DECOM	
19940701	20120305	20110302	Occurred during P&A activities on a terminated lease.	DECOM	
20001201	20110613	20100216	Occurred during P&A activities on a terminated lease.	DECOM	
			Occurred during well abandonment operations on a		
19730201	20110418	20100601	terminated lease.	DECOM	
			Occurred during well abandonment operations on a		
19970201	20100929	20030805	terminated lease.	DECOM	
			Occurred during permanent abandonment operations on a		
19740501	20100528	20080709	terminated lease.	DECOM	

			Occurred during well abandonment operations on a	
19550101	20100417	20100308	terminated lease.	DECOM
			Incident associated with the PA of a toppled platform on	
19750701	20090826	20090430	terminated lease.	DECOM
			Occurred during permanent abandonment operations on a	
19830701	20090712	20081027	terminated lease.	DECOM
			Occurred during permanent abandonment operations on a	
19811201	20090501	20070628	relinquished lease.	DECOM
			Incident occurred during rig demobilization associated with	
19890501	20080713	20060731	abanondment work on a relinquished lease.	DECOM
20020701	20080610	20070911	Occurred during facility decommissioning on an expired lease.	DECOM
			Occurred during facility decommissioning on a relinquished	
19801101	20080413	20060731	lease.	DECOM
			Occurred during permanent abandonment operations on a	
19760401	20080106	20050713	terminated lease.	DECOM
			Duplicate reports - abandonment operations on a terminated	
19940101	20070211	20020727	lease.	DECOM
			Duplicate reports - abandonment operations on a terminated	
19940101	20070210	20020727	lease.	DECOM
			Incident occurred in plug and abandonment work on a	
19750901	20060220	20040717	terminated lease	DECOM
			Incident associated with a permanent plugg operation with a	
19970801	20030705	20020731	dive boat - well stub removal.	DECOM
			Incident occurred in plug and abandonment work on a	
19800101	19961207	19951004	terminated lease.	DECOM
			Incident occurred during decommissioning operations of RUE	
19450828	20110522	20070505	platforms previously associated with Lease OCS 0054.	DECOM-RUE

			Transocean Rig 96 was being towed by 3 tugs in the Ship Shoal	
			332 area when a motor failed and dropped an anchor cable. The anchor dragged across a 24" Poseidon Pipeline.	
			Approximately 1800 bbls of crude oil was release from the	
19810901	20000121	19921230	line.	INDEP
19960701	20091230	20070527	Pollution incident associated with an expired lease.	POLL
19860701	19970619	19910816	PA Well leaking - E1 well was bubbling and caused a sheen.	POLL
			G09762 expired on 2/12/94. Pollution incident on expired	
19880801	19960309	19940212	lease.	POLL
			Event occurred on a RUE platform with previous authority of	
20030701	20030529	20120601	lease G01014.	PROD
			The incident occurred on a jackup rig on site to sidetrack a well	
			that surfaced on an RUE platform (previously associated with lease G22606) to a bottom hole location on a neighboring	
20010701	20130531	20100707	block.	RUE
20010701	20130331	20200707	Flowing pipeline assoicated with hurricane dame on an	
20020501	20090725	20070430	expired lease.	POLL
			The incident occurred on a platform (pending RUE) which was being maintained to process production from a well on	
19620501	20081130	20080511	another lease.	RUE
			Work associated with equipment repairs on an RUE platform	
19541201	20080405	20031020	formally associated with the terminated lease.	RUE
40070704	20000224	20050422	incident associated with a derrick barge under tow - barge	INIDED
19970701	20080301	20050123	made contact with a platform in the EI 43 field.	INDEP

			Incident occurred on the deck of a motor vessel and wouldn't fall under our jurisdiction. IP was tieing up to a Marathon	
19721001	20071115	20030220	platform according to report.	INDEP
			OCS-G 02181 expired on 2/5/92; however, the lease OCS-	
19721101	20070823	19920205	G02940 is still a active primary lease on the same area/block.	PROD
			A mixture of diesel fuel and parafin wax spilled into the gulf	
			from a valve on a storage tank on board the vessel (Q-4000).	
			Incident associated with pipeline repairs - A coil tubing unit	
			was rigged up to the pipeline at Green Canyon 177 to clean	
19960901	20070217	20050331	out a paraffin plug.	POLL
			Platform on which this incident took place is associated with	
			ROW G18794 which became effective 9/26/2007, albeit	
19910701	20070204	20060227	belatedly.	ROW
			Platform on which this incident took place was associated with	
19830701	20050820	20001212	RUE G23645.	RUE
			Platform on which incident took place was associated with	
19770801	20050624	20020618	RUE G30071.	RUE
			Platform on which incident took place was associated with	
19680701	20040718	19980403	RUE G23672.	RUE
			Platform on which incident took place was associated with	
19801101	20031128	19940409	ROW G15988.	ROW
			The terminated lease expired on 11/1/2003. Incident occurred	
			3 weeks later. Classify as DECOM assuming incident occurred	
19620501	20031121	20031101	while maintaining facility until DECOM.	DECOM
			Helicopter crash - not under our jurisdiction. The lease at the	
			time the accident occurred was OCS-G16502 that was	
			effective on $7/1/96$ and expired on $7/25/07$ . The platform	
19760401	20030116	19960220	that was involved was associated with ROW G22103.	ROW

19811201	20011010	20000322	Platform on which this incident occurred was belatedly transferred to an RUE authority G23617 in order to produce 2 wells which bottom holed on neighboring leases.  The platform on which this incident occurred was associated with ROW G21469 which was active from 6/28/2000 through 3/27/2001. The platform authority has since been transferred	RUE
19810901	20000816	19971110	to lease G19863.  ST 53 had a lease (OCS-G 04000) affiliated with the area/block at the time of the incident that was producing and is still active today. The lease was effective3/1/79 and the platform	ROW
19480717	20000815	19580715	was installed in 1980.  The platform on which this incident occurred had been transferred to ROW G15985. On 11/19/2003 the authority	PROD
19810101	20000405	19950927	was again transferred to lease G17182.	ROW
19670601	19990907	19880731	This pollution incident occurred on a ROW platform, G04282.	POLL
19810901	19981022	19921230	Platform authority transferred to ROW G14094 on 12/27/1993. This ROW was relinq on 2/25/2002. Incident ocurred during this time.  While welding on a crane gas was expelled from a 2900 controller on a nearby test seperator. The area/block had been releases as G13628 which was producing when the incident occurred. The platform authority history does not	ROW
19750701	19980328	19910806	reflect the transfer of the platform to the new lease.	PROD
19840601	19970821	19951204	Incident associated with well PA operations following lease expiration.	DECOM