	00 BP 00 Type De		
Application Status Approved Operator 01560 Pacific Operator	perators Offshore, I	LLC	
Pay.gov Agency	Pay.gov		
Amount: Tracking ID:	Tracking ID:		
General Information			
API 043112008100 Approval Dt 08-MAR-2018	Approved By Jo	ohn Kaiser	
Submitted Dt 10-OCT-2017 Well Status Completed	Water Depth 1	54	
Surface Lease P00166 Area LA	Block	660	
Approval Comments	01	560	
Conditions of Approval: 1) All operations must be conducted in accordance with the			
Operators (NTLs), the approved (revised) Application for Perany written instructions or orders of the District Manager. 2) While you are on the well and observe a pressure that exits in the approved permit, the equipment in use must be tested observed pressure and the appropriate District must be noting. 3) A copy of this permit (including all attachments) must be available to inspectors upon request during the permitted of 4) A revised PE certification is needed if (1) the plug type changes in cement properties, (2) any plug's setting depth required per 250.1715), changes ± 100 ' TVD, (3) the pressure hydrocarbon zone that was not anticipated in the original permit, or you deviate from the §250.1715 table. 5) Notify the Permitting Section at Least 24 hours in advant operations AND of any required BOP tests. 6) Notify the Permitting section at least 24 hours in advant testing a plug.	acceeds the test press d to at or greater to lified of this pressur- operation. De changes in any wa (even the ones that are test changes on ed in order to isolar bermit, (6) a remedi or (7) any plug char and the of beginning the	ssures stated than the are change. and made ay including t are not any plug, (4) ate a al cement job age that makes ese approved	
7) WAR reports are due no later than noon each Wednesday. 3) When the new BOP arrives, a copy of all the BOP S53 comp must be provided to this office. Inspection reports have b 9) The Compliance Section has inspected the new BOP and doc placed in service.	peen attached to thi	s permit.	
Correction Narrative			
Driginal submitted program was revised and consequently res from the 3rd party.	submitted with the c	ertification	
The Double Ram file was over 20MB and had to be separated i	into two files, (A)	and (B).	
The complete assembled BOPE was successfully chart tested a l1-15-2017. The test results are on file in the tool pushe	-	et Miller on	
Permit Primary Type Abandonment Of Well Bore			
Permit Subtype(s)			
Temporary Abandonment			
Temporary Abandonment Dperation Description			

BSEE FORM BSEE-0124

Applica	tion Status App								evelopment
Application Status Approved Operator 01560 Pacific Operators Offshore, LLC							LLC		
Perfora	te with 4SPF at	1710 and e	stablish	circulati	on.				
(minimu	etainer at 1660' m 200' of annula 10-3/4" annulus	ar fill + 5	0' below		-				
Spot 9.	5 ppg abandonmer	nt mud from	TOC to	500'.					
	etainer at 500' al abandonment p		ement to	fill at l	east to	350' OI	RKB abov	ve the	e retainer as
Subsurf	ace Safety Valve)							
Туре	Installed N/A								
Feet	below Mudline								
Maxi	mum Anticipated	Surface Pr	essure (psi) 135					
Shut	-In Tubing Pres	sure (psi)	110						
Rig In	formation								
Name		Ic	1	Туре		ABS D	ate	Coa	st Guard Date
* PLAT	FORM RIG TO BE I	DETERMINI 60		PLATFORM			C-2019		DEC-2019
Blowou	t Preventers					Toot Dr	essure		
Preven	ter	Size	Worki	ng Pressur			High		
Rams		12	3000		250		750		
Annula	r		3000		250		750		
Date Co	mmencing Work (n	m/dd/vvvv)	26-MAR-	2017					I
	ed duration of t								
	Approval Inf			, '					
Verbar	Official	Ormacion		Date (mm/	dd (ynnor)				
Ouesti									
2	Question			Response	Respons	e Text			
1	Is H2S present yes, then comme inclusion of a for this operat	ent on the Contingenc		NO					
2	Is this propose only lease hold the subject lea comment.	ed operatic ding activi	ty for	NO					
3	Will all wells and related pro be shut-in when off of an offs from well to we platform? If no explain.	oduction eq n moving on nore platfo ell on the	uipment to or	NO					rame on an s in the well

Quest	ions					
~	er Question	Respo	nse Response Text			
4	Are you downhole commingling tw or more reservoirs?	o NO				
5	Will the completed interval be within 500 feet of a lease or unit boundary line? If yes, then comment.	NO				
6	For permanent abandonment, will casings be cut 15 feet below th mudline? If no, then comment.		Permanent well abandonment will be done at time of platform abandonment			
7	Will the proposed operation be covered by an EPA Discharge Permit? (Please provide permit number in comments for this question)		IENTS			
File I odf			Abandonment Program			
odf	Annular BOP Seria					
odf Annular BOP Diagram						
pdf Double Ram BOP d						
pdf Double Ram BOP 170						
pdf Double Ram BOP 170						
pdf Proposed Wellbore S			zic			
pdf Current Wellbore Sc			ic			
pdf	BOP testing proce	edure				
odf	Revised BOP scher					
		CONTA	CTS			
Name	Ronald Nazeley					
Company Pacific Operators C		s Offsho	re, LLC			
Phone	Number 805-899-3144					
E-mai	1 Address nazeley@pacops.co	ley@pacops.com				
Contact Description Chief Engineer						

CERTIFICATION: I certify that information submitted is complete and accurate to the best of my knowledge. I understand that making a false statement may subject me to c1

Name and Title

Date

Ronald Nazeley, VP & Chief Engineer

27-FEB-2018

PAPERWORK REDUCTION ACT OF 1995 (PRA) STATEMENT: The PRA (44 U.S.C. 3501 et seq. Requires us to inform you that we collect this information to obtain knowledge of equipment and procedures to be used in drilling operations. MMS uses the information to evaluate and approve or disapprove the adequacy of the equipment and/or procedures to safely perform the proposed drilling operation. Responses are mandatory (43 U.S.C. 1334). Proprietary data are covered under 30 CFR 250.196. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB Control Number. Public reporting burden for this form is estimated to average 11/4 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to the Information Collection Clearance Officer, Mail Stop 4230, Minerals Management Service, 1849 C Street, N.W., Washington, DC 20240.